

ISO 5543:2004-12 (E)

Caseins and caseinates - Determination of fat content - Gravimetric method (Reference method)

Contents		Page
Foreword		iv
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	1
5	Reagents	1
6	Apparatus and materials	2
7	Sampling	3
8	Procedure	3
8.1	Preparation of test sample	4
8.2	Test portion	4
8.3	Blank test	4
8.4	Preparation of fat-collecting vessel	4
8.5	Determination	4
9	Calculation and expression of results	7
10	Precision	8
10.1	Interlaboratory test	8
10.2	Repeatability	8
10.3	Reproducibility	8
11	Notes on procedure	8
11.1	Blank test to check the reagents	8
11.2	Blank test carried out simultaneously with the determination	9
11.3	Test for peroxides in diethyl ether	9
11.4	Diethyl ether containing antioxidants	9
12	Test report	10
Annex A (informative)	Alternative procedure using fat-extraction tubes with siphon or wash- bottle fittings	11
Bibliography		14