

# ISO 16063-13:2001-12 (E)

## Methods for the calibration of vibration and shock transducers - Part 13: Primary shock calibration using laser interferometry

---

<b>Contents</b>		<b>Page</b>
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Uncertainty of measurement .....</b>	<b>1</b>
<b>4</b>	<b>Requirements for apparatus .....</b>	<b>2</b>
4.1	General .....	2
4.2	Shock machine based on rigid body motion of an anvil .....	2
4.3	Shock machine based on wave propagation inside a long thin bar .....	2
4.4	Seismic block(s) for shock machine and laser interferometer .....	4
4.5	Laser .....	4
4.6	Interferometer .....	4
4.7	Oscilloscope .....	7
4.8	Waveform recorder with computer interface .....	7
4.9	Computer with data-processing program .....	7
4.10	Filters .....	7
4.11	Other requirements .....	7
<b>5</b>	<b>Ambient conditions .....</b>	<b>8</b>
<b>6</b>	<b>Preferred accelerations and pulse durations .....</b>	<b>8</b>
<b>7</b>	<b>Method .....</b>	<b>8</b>
7.1	Test procedure .....	8
7.2	Data acquisition .....	9
7.3	Data processing .....	9
<b>8</b>	<b>Reporting the calibration results .....</b>	<b>13</b>
<b>Annexes A Expression of uncertainty of measurement in calibration .....</b>		<b>14</b>
<b>B</b>	<b>Explanation of the procedures .....</b>	<b>16</b>
<b>C</b>	<b>Alternative method of calculation of magnitude and phase shift of the complex sensitivity .....</b>	<b>20</b>
<b>Bibliography .....</b>		<b>22</b>