

ISO 16063-13:2001-12 (E)

Methods for the calibration of vibration and shock transducers - Part 13: Primary shock calibration using laser interferometry

Contents		Page
1	Scope	1
2	Normative references	1
3	Uncertainty of measurement	1
4	Requirements for apparatus	2
4.1	General	2
4.2	Shock machine based on rigid body motion of an anvil	2
4.3	Shock machine based on wave propagation inside a long thin bar	2
4.4	Seismic block(s) for shock machine and laser interferometer	4
4.5	Laser	4
4.6	Interferometer	4
4.7	Oscilloscope	7
4.8	Waveform recorder with computer interface	7
4.9	Computer with data-processing program	7
4.10	Filters	7
4.11	Other requirements	7
5	Ambient conditions	8
6	Preferred accelerations and pulse durations	8
7	Method	8
7.1	Test procedure	8
7.2	Data acquisition	9
7.3	Data processing	9
8	Reporting the calibration results	13
Annexes A Expression of uncertainty of measurement in calibration		14
B	Explanation of the procedures	16
C	Alternative method of calculation of magnitude and phase shift of the complex sensitivity	20
Bibliography		22