

ISO/TR 10064-6:2009-02 (E)

Code of inspection practice - Part 6: Bevel gear measurement methods

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms, definitions and symbols	2
3.1	Terms and definitions	2
3.2	Symbols	3
4	Bevel gear measurement	4
4.1	Manufacturing and purchasing considerations	4
4.2	Manufacturing documentation	5
4.3	Process control	5
4.4	Measurement methods	5
4.5	Additional considerations	6
4.6	Acceptance criteria	7
5	Measuring methods and practices	7
5.1	Guidelines for measurement of gear characteristics	7
5.2	Measuring practices	8
5.3	Measurement of pitch deviations	10
5.4	Measurement of bevel gear runout	16
5.5	Flank form measurement	18
5.6	Contact pattern checking	25
5.7	Single-flank composite inspection	30
5.8	Double-flank composite testing	30
5.9	Tooth thickness measurement	33
5.10	Manufacturing applications	36
6	Recommended datum surface tolerances	36
Bibliography		37