

DIN EN 1870-12:2010-07 (E)

Safety of woodworking machines - Circular sawing machines - Part 12: Pendulum cross-cut sawing machines (includes Amendment A1:2009)

Contents		Page
Foreword		4
0	Introduction	6
1	Scope	6
2	Normative references	7
3	Terms and definitions	9
4	!!!!List of significant hazards""""	11
5	Safety requirements and/or measures	14
5.1	Controls	14
5.1.1	Safety and reliability of control systems	14
5.1.2	Position of controls	15
5.1.3	Starting	17
5.1.4	Normal stopping	18
5.1.5	Emergency stop	19
5.1.6	Integrated feed	19
5.1.7	Mode selection	20
5.1.8	Failure of the power supply	20
5.1.9	Failure of the control circuits	20
5.2	Protection against mechanical hazards	20
5.2.1	Stability	20
5.2.2	Risk of break up during operation	21
5.2.3	Tool holder and tool design	21
5.2.4	Braking	22
5.2.5	Devices to minimise the possibility or effect of ejection	24
5.2.6	Workpiece supports and guides	24
5.2.7	Prevention of access to moving parts	26
5.2.8	Clamping devices	30
5.3	Protection against non-mechanical hazards	30
5.3.1	Fire	30
5.3.2	Noise	31
5.3.3	Emission of chips and dust	32
5.3.4	Electricity	32
5.3.5	Ergonomics and handling	32
5.3.6	Pneumatics	33
5.3.7	Hydraulics	33
5.3.8	!!!!Electromagnetic compatibility""""	33
5.3.9	Laser	33
5.3.10	Static electricity	34
5.3.11	Errors of Fitting	34
5.3.12	Isolation	34
5.3.13	Maintenance	34
6	Information for use	35
6.1	Warning devices	35
6.2	Marking	35
6.3	Instruction handbook	36

Annex A (informative) Examples of safety related control systems with electronic components	39
Annex B (normative) Dimensional tolerances of saw spindles	43
Annex ZA (informative) !!!!Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC""""	45
Annex ZB (informative) !!!!Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC""""	46
Bibliography	47