

DIN EN 13042-1:2010-04 (E)

Machines and plants for the manufacture, treatment and processing of hollow glass - Safety requirements - Part 1: Gob feeder (includes Amendment A1:2009)

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	6
4	List of significant hazards	6
5	Safety requirements and/or protective measures	8
5.1	General	8
5.2	Starting and stopping and unexpected start-up	8
5.3	Emergency-stop equipment	8
5.4	Avoiding slip hazard	8
5.5	Design of manual controls	9
5.6	Guards	9
5.7	Lockout of shears	9
5.8	Hydraulic/pneumatic system	9
5.9	Electrical equipment	9
5.10	Energy supply disconnecting devices	9
5.11	Gob-loading interruption	9
5.12	Quick release refractory chucks	10
5.13	Refractory lifting device	10
5.14	Glass flow	10
5.15	Necessary movements in case of power failure	10
5.16	Safeguarding against contact with hot surfaces	10
5.17	Noise	10
6	Verification of safety requirements and/or protective measures	11
7	Information for use	12
7.1	General	12
7.2	Accompanying documents (in particular: Instruction handbook)	12
7.3	Marking	13
Annex A (informative) Glossary		15
Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC		16
Annex ZB (informative) !!!!Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC""""		17
Bibliography		18
Tables !!!!Table 1 -- List of significant hazards""""		6
!!!!Table 2 -- Individual testing for requirements stated in Clause 5""""		12