

# DIN EN 13042-1:2010-04 (E)

## Machines and plants for the manufacture, treatment and processing of hollow glass - Safety requirements - Part 1: Gob feeder (includes Amendment A1:2009)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	6
4	List of significant hazards .....	6
5	Safety requirements and/or protective measures .....	8
5.1	General .....	8
5.2	Starting and stopping and unexpected start-up .....	8
5.3	Emergency-stop equipment .....	8
5.4	Avoiding slip hazard .....	8
5.5	Design of manual controls .....	9
5.6	Guards .....	9
5.7	Lockout of shears .....	9
5.8	Hydraulic/pneumatic system .....	9
5.9	Electrical equipment .....	9
5.10	Energy supply disconnecting devices .....	9
5.11	Gob-loading interruption .....	9
5.12	Quick release refractory chucks .....	10
5.13	Refractory lifting device .....	10
5.14	Glass flow .....	10
5.15	Necessary movements in case of power failure .....	10
5.16	Safeguarding against contact with hot surfaces .....	10
5.17	Noise .....	10
6	Verification of safety requirements and/or protective measures .....	11
7	Information for use .....	12
7.1	General .....	12
7.2	Accompanying documents (in particular: Instruction handbook) .....	12
7.3	Marking .....	13
Annex A (informative) Glossary .....		15
Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC .....		16
Annex ZB (informative) !!!!Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC"""" .....		17
Bibliography .....		18
Tables !!!!Table 1 -- List of significant hazards"""" .....		6
!!!!Table 2 -- Individual testing for requirements stated in Clause 5"""" .....		12