

DIN EN 1822-2:2011-01 (E)

High efficiency air filters (EPA, HEPA and ULPA) - Part 2: Aerosol production, measuring equipment, particle counting statistics

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Aerosol production	5
4.1	General	5
4.2	Aerosol substances	5
4.3	Producing monodisperse aerosols	7
4.3.1	Condensation methods	7
4.3.2	Particle size classification	11
4.4	Generating polydisperse aerosols	11
4.5	Neutralisation of aerosols	11
4.6	Minimum performance parameters for aerosol generators	12
4.7	Sources of error	12
4.8	Maintenance and inspection	12
5	Measuring devices	12
5.1	Optical particle counters	12
5.1.1	Operation	12
5.1.2	Minimum performance parameters	13
5.1.3	Sources of error and limit errors	14
5.1.4	Maintenance and inspection	14
5.1.5	Calibration	14
5.2	Condensation nucleus counter	14
5.2.1	Operation	14
5.2.2	Minimum performance parameters	16
5.2.3	Sources of error and limit errors	16
5.2.4	Maintenance and inspection	17
5.2.5	Calibration	17
5.3	Differential mobility analyser	17
5.3.1	Operation	17
5.3.2	Minimum performance parameters	18
5.3.3	Sources of error and limit errors	18
5.3.4	Maintenance and inspection	19
5.3.5	Calibration	19
5.4	Particle size analysis system on the basis of differential mobility analysis	19
5.4.1	Operation	19
5.4.2	Minimum performance parameters	19
5.4.3	Sources of errors and error limits	19
5.4.4	Maintenance and inspection	19
5.4.5	Calibration	19
5.5	Dilution systems	20
5.5.1	Operation	20
5.5.2	Minimum performance parameters	20
5.5.3	Sources of error and limit errors	20

5.5.4	Maintenance and inspection	20
5.6	Differential pressure measuring equipment	20
5.7	Absolute pressure measuring equipment	21
5.8	Thermometers	21
5.9	Hygrometer	21
6	Maintenance and inspection intervals	21
7	Particle counting statistics	23
	Bibliography	25