

DIN EN 1822-4:2011-01 (E)

High efficiency air filters (EPA, HEPA and ULPA) - Part 4: Determining leakage of filter elements (scan method)

| Contents | | Page |
|--------------------|---|-------------|
| Foreword | | 4 |
| Introduction | | 5 |
| 1 | Scope | 6 |
| 2 | Normative references | 6 |
| 3 | Terms and definitions | 6 |
| 4 | Description of the procedure | 7 |
| 5 | Test filter | 8 |
| 6 | Test apparatus | 8 |
| 6.1 | Set-up of the test apparatus | 8 |
| 6.2 | Test duct | 11 |
| 6.2.1 | Test air conditioning | 11 |
| 6.2.2 | Adjustment of the volume flow rate | 11 |
| 6.2.3 | Measurement of the volume flow rate | 11 |
| 6.2.4 | Aerosol mixing duct | 11 |
| 6.2.5 | Test filter mounting assembly | 11 |
| 6.2.6 | Measuring points for the pressure difference | 11 |
| 6.2.7 | Sampling, upstream | 11 |
| 6.2.8 | Screening | 12 |
| 6.3 | Scanning assembly | 12 |
| 6.3.1 | General | 12 |
| 6.3.2 | Sampling, downstream | 12 |
| 6.3.3 | Probe arm | 13 |
| 6.3.4 | Aerosol transport lines | 13 |
| 6.3.5 | Provisions to move the probe | 13 |
| 6.4 | Aerosol generation and measurement techniques | 13 |
| 6.4.1 | General | 13 |
| 6.4.2 | Set-up for testing with a monodisperse test aerosol | 14 |
| 6.4.3 | Set-up for testing with a polydisperse test aerosol | 14 |
| 7 | Test air | 14 |
| 8 | Test procedure | 15 |
| 8.1 | General | 15 |
| 8.2 | Preparatory checks | 15 |
| 8.3 | Starting up the aerosol generator | 16 |
| 8.4 | Preparing the test filter | 16 |
| 8.4.1 | Installing the test filter | 16 |
| 8.4.2 | Flushing the test filter | 16 |
| 8.5 | Testing | 16 |
| 8.5.1 | Measuring the pressure drop | 16 |
| 8.5.2 | Testing with monodisperse test aerosol | 17 |
| 8.5.3 | Testing with polydisperse test aerosol | 17 |
| 8.5.4 | Leak testing (local penetration) | 17 |
| 8.5.5 | Determining the mean efficiency of the filter element | 17 |

| | | |
|--|---|-----------|
| 9 | Evaluation | 18 |
| 9.1 | Calculating the penetration and the efficiency | 18 |
| 9.2 | Local penetration | 19 |
| 9.3 | Mean efficiency | 20 |
| 9.4 | Classification | 20 |
| 10 | Test report | 20 |
| 11 | Maintenance and inspection of the test apparatus | 21 |
| Annex A (normative) Oil Thread Leak Test | | 23 |
| Annex B (normative) Determining the test parameters | | 24 |
| B.1 | General | 24 |
| B.2 | Boundary conditions | 24 |
| B.3 | Test filter data | 24 |
| B.4 | Data for the apparatus | 25 |
| B.4.1 | Particle counters | 25 |
| B.4.2 | Downstream sampling probes | 25 |
| B.4.3 | Loss factor | 26 |
| B.5 | Sequence of calculation steps | 26 |
| B.6 | Checking the isokinetic sampling | 27 |
| B.7 | Choosing the probe speed | 28 |
| B.8 | Minimum aerosol concentration | 29 |
| B.9 | Maximum aerosol concentration | 30 |
| B.10 | Leak signal | 31 |
| B.10.1 | Effective value | 31 |
| B.10.2 | Signal difference | 32 |
| Annex C (informative) Example of an application with evaluation | | 34 |
| Annex D (informative) Leak Test with solid PSL Aerosol | | 37 |
| D.1 | Background | 37 |
| D.2 | General Remarks | 37 |
| D.3 | Test Procedure | 37 |
| D.4 | Test Protocol | 39 |
| Annex E (informative) 0,3 µm - 0,5 µm Particle Efficiency Leak Test | | 40 |
| Bibliography | | 42 |