

ISO 14291:2012-07 (E)

Vacuum gauges - Definitions and specifications for quadrupole mass spectrometers

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Terms and definitions	1
2.1	Definitions of components	1
2.2	Definitions of physical parameters	5
3	Symbols and abbreviated terms	8
4	Principle of QMS	9
5	Specifications for a QMS to be provided by manufacturers	9
5.1	Mass range	9
5.2	Type of ion source	9
5.3	Type of ion detector	9
5.4	Mass resolution	10
5.5	Mass number stability	10
5.6	Sensitivity	10
5.7	Linear response range	10
5.8	Minimum detectable partial pressure	10
5.9	Minimum detectable concentration	10
5.10	Maximum operational pressure	10
5.11	Scanning parameter	10
5.12	Signal output	11
5.13	Potentials	11
5.14	Detector specifications	11
5.15	Set point	11
5.16	Maximum bake-out temperature	11
5.17	Nominal operating conditions	11
5.18	Warm-up time	11
5.19	Filament material	11
5.20	Electron emission current	11
5.21	Filament exchange	11
5.22	Detector exchange	11
5.23	Fitting to chamber	12
5.24	Mounting orientation	12
5.25	Dimensions	12
5.26	Internal volume	12
5.27	Mass of sensor head and electronic unit	12
5.28	Input power of electronic unit	12
5.29	Cable	12
5.30	Software	12
5.31	Interface	12
5.32	Storage and transportation condition	12
6	Optional specifications for QMS to be provided by manufacturers	13
6.1	Mass resolution	13
6.2	Fragmentation or cracking pattern	13
6.3	Temperature coefficient of sensitivity	13

6.4	QMS sensor cleaning	13
6.5	Degassing	13
6.6	Degassing power	13
6.7	Photographs	13
6.8	Inspection record	13
6.9	Outgassing rate	13
	Bibliography	14