

DIN EN 415-10:2014-07 (E)

Safety of packaging machines - Part 10: General requirements

Contents		Page
Foreword		5
Introduction		6
1	Scope	7
2	Normative references	7
3	Terms and definitions	10
4	List of significant hazards	11
4.1	General	11
4.2	Mechanical hazards	12
4.2.1	Moving parts	12
4.2.2	Slip, trip and fall hazards	12
4.2.3	Loss of stability	12
4.2.4	Hazards from guards	12
4.3	Pneumatic and hydraulic equipment	12
4.4	Hazards from electrical equipment	13
4.5	Hazards from electrostatic phenomena	13
4.6	Thermal hazards	13
4.6.1	Hot Surfaces	13
4.6.2	Cold surfaces	13
4.7	Noise	13
4.8	Radiation	13
4.9	Hazards from products and materials	14
4.9.1	Hazards generated by products	14
4.9.2	Hazards generated by packaging materials	14
4.10	Hazards due to neglecting ergonomic principles	15
4.11	Hazards due to neglecting hygienic design principles	15
4.12	Hazards caused by failures	15
4.12.1	General	15
4.12.2	Failure of power supplies	15
4.12.3	Failure of safety related parts of control systems	16
4.12.4	Failure of electronic drive systems	16
4.13	Hazards caused by the presence of stored energy	16
4.14	Hazards due to remote diagnostics or control	16
4.15	Reasonably foreseeable misuse	16
4.16	Hazards from specific elements or processes of packaging machines	17
4.16.1	Cutting devices	17
4.16.2	Sealing devices	17
4.16.3	Film reel unwind mechanisms	18
4.16.4	Conveyors	18
4.16.5	Handles and hand-wheels	20
4.16.6	Size or product changing	20
4.16.7	Hot melt adhesive equipment	21
4.16.8	Modified atmosphere packaging	21
5	Safety requirements and/or protective measures	21
5.1	General	21
5.2	Requirements to minimize mechanical risks	22
5.2.1	Protective measures against risks from moving parts	22

5.2.2	Requirements to prevent slip, trip and fall hazards	52
5.2.3	Stability of machines	52
5.2.4	Prevention of hazards from movable guards	53
5.3	Supply disconnecting (isolating) device	53
5.4	Pneumatic and hydraulic equipment	53
5.5	Electrical equipment	54
5.5.1	General	54
5.5.2	Protection against electric shock	54
5.5.3	Degree of protection	54
5.6	Electrostatic phenomena	54
5.7	Thermal hazards	55
5.7.1	Hot surfaces	55
5.7.2	Cold surfaces	55
5.8	Noise reduction	55
5.9	Radiation	56
5.9.1	General	56
5.9.2	Laser radiation	56
5.10	Measures to control hazards generated by products, substances and materials	57
5.10.1	Measures to control hazards generated by substances	57
5.10.2	Measures to control hazards generated by products	57
5.10.3	Measures to control hazards generated by packaging materials	59
5.11	Ergonomic design principles	60
5.11.1	Operating the machine	60
5.11.2	Operator interface and machine mounted control devices	60
5.11.3	Handling machine parts	60
5.11.4	Loading packaging materials	60
5.11.5	Loading products or unloading packages	61
5.11.6	Size or product changes	61
5.11.7	Cleaning the machine	61
5.11.8	Maintenance	61
5.11.9	Moving the machine	61
5.11.10	Lighting	62
5.12	Hygienic design requirements	62
5.13	Failures of power supplies	62
5.14	Control functions	63
5.14.1	General	63
5.14.2	Normal stop	63
5.14.3	Safety related stop functions	63
5.14.4	Operational stop	63
5.14.5	Emergency stop and emergency switching off	63
5.14.6	Safety related stops of variable speed electrical power drive systems	64
5.14.7	Stopping time	65
5.15	Failures of safety related parts of control systems	65
5.16	Prevention of unexpected start up	65
5.16.1	General	65
5.16.2	Requirements for machines where whole body access is possible	65
5.16.3	Operations with open guards	66
5.17	Stored energy	67
5.18	Requirements for remote diagnostics or control	67
5.19	Reasonably foreseeable misuse	68
5.20	Requirements for specific elements or processes of packaging machines	68
5.20.1	Cutting devices	68
5.20.2	Sealing devices	69
5.20.3	Film reel unwind mechanisms	69
5.20.4	Conveyors	69
5.20.5	Handles and hand-wheels	72
5.20.6	Size or product changing	72
5.20.7	Hot melt adhesive equipment	73
5.20.8	Modified atmosphere packaging	74
6	Verification of safety requirements and measures	74
6.1	General	74

6.2	Visual inspections with the machine stopped	75
6.2.1	Mechanical parts	75
6.2.2	Pneumatic systems	75
6.2.3	Hydraulic systems	75
6.2.4	Electrical systems	75
6.2.5	Guards	75
6.2.6	Design requirements	75
6.2.7	Marking and warning signs	75
6.3	Measurements with the machine stopped	75
6.3.1	Guards	75
6.3.2	Electrical testing	75
6.4	Visual inspections with the machine running	76
6.4.1	Guards	76
6.4.2	Safety related functions	76
6.4.3	Dissipation of stored energy	76
6.5	Measurements or tests with the machine running	76
6.5.1	Electrical testing	76
6.5.2	Measurement of noise emission	76
6.5.3	Temperature	76
6.6	Verification procedures	76
7	Information	78
7.1	General	78
7.2	Marking	78
7.3	Signals and warning signs	78
7.3.1	General	78
7.3.2	Prohibition sign "Do not reach in"	79
7.3.3	Prohibition sign "No access"	79
7.3.4	Warning sign "Hot surface"	80
7.3.5	Warning sign "Warning; Low temperature/freezing conditions"	80
7.3.6	Warning signs indicating radiation hazards	81
7.3.7	Prohibition sign "Access prohibited for persons with implantable medical devices"	83
7.4	Instructions	83
7.4.1	General	83
7.4.2	All packaging machines	84
7.4.3	Machines for use with foodstuffs or pharmaceuticals	85
7.4.4	Machines for handling hazardous products	85
7.4.5	Machines with hot or cold surfaces	85
7.4.6	Machines incorporating hot melt and other adhesive systems	85
7.4.7	Information on stability of the machine	85
7.4.8	Machines incorporating lifting equipment	86
7.4.9	Assemblies of machines	86
	Annex A (informative) Evaluation of energy or force	87
	Annex B (informative) Maximum values for inherently safe design	88
	Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC	89
	Bibliography	92