

DIN EN ISO 16891:2016-12 (E)

Test methods for evaluating degradation of characteristics of cleanable filter media (ISO 16891:2016)

Contents		Page
European foreword		3
Foreword		4
Introduction		5
1	Scope	6
2	Normative references	6
3	Terms and definitions	6
4	Symbols and abbreviated terms	9
5	Principle	10
6	Test specimen, equipment and test procedure	11
6.1	General.....	11
6.2	Preparation of sheets for gas exposure.....	12
6.2.1	Shape and size of tensile specimen.....	12
6.2.2	Sample sheet for exposure.....	12
6.2.3	Selection of sample sheet through air permeability measurement.....	13
6.2.4	Filter media for exposure.....	13
6.3	Sample preparation.....	14
6.3.1	Exposure system.....	14
6.3.2	Heating system.....	16
6.3.3	Test gas supply system.....	16
6.3.4	Gas analyzer.....	16
6.3.5	Gas treatment device.....	17
6.4	Exposure conditions and procedures.....	17
6.4.1	Exposure conditions.....	17
6.4.2	Exposure period and number of exposure.....	17
6.4.3	Attachment of filter sample sheets in the sample case.....	18
6.4.4	Implementation of the exposure.....	18
7	Tensile strength measurement of exposed specimen	19
7.1	Tensile test device.....	19
7.2	Preparation of a tensile test specimen.....	19
7.3	Method of tensile test.....	19
7.4	Characterization of the degradation.....	20
8	Test report	21
Annex A (informative) Causes and results of degradation of fabrics		22
Annex B (informative) Possible evaluation method for characteristic change of fabrics		23
Annex C (informative) Theoretical consideration of degradation mechanism		24
Annex D (informative) Determination of specimen size		27
Annex E (informative) Experimental setup for gas exposure		31
Annex F (informative) Service temperature of filter materials		35
Annex G (informative) Examples of measured data of fabric at different circumstances		36
Annex H (informative) Example of test report		42
Bibliography		46