

ISO/TR 10064-1:2017-07 (E)

Code of inspection practice - Part 1: Measurement of cylindrical gear tooth flanks

| Contents | | Page |
|-----------------|--|-------------|
| Foreword | | vi |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms, definitions, symbols and abbreviated terms | 1 |
| 4 | General considerations | 5 |
| 4.1 | Background | 5 |
| 4.2 | Required inspection information | 5 |
| 4.3 | Measurement selection | 5 |
| 4.3.1 | Substitution of measurement methods | 5 |
| 4.3.2 | First piece inspection | 5 |
| 4.3.3 | Sampling and statistical process control | 5 |
| 5 | Conventions and measurement positions | 6 |
| 5.1 | General | 6 |
| 5.2 | Datum axis | 6 |
| 5.3 | Left or right flank | 6 |
| 5.4 | Left hand or right hand helical gears | 7 |
| 5.5 | Numbering of teeth and flanks | 7 |
| 5.6 | Numbering of pitches | 8 |
| 5.7 | Number of pitches "k" in a deviation symbol subscript | 8 |
| 6 | Types of measuring equipment and principle | 8 |
| 6.1 | General | 8 |
| 6.2 | Measurement methods | 14 |
| 6.2.1 | Generative measurement methods | 14 |
| 6.2.2 | Non-generative measurement methods | 16 |
| 6.2.3 | Pitch measurement methods | 17 |
| 6.2.4 | Hand-held pitch measuring devices | 18 |
| 6.2.5 | Radial runout measurement | 20 |
| 6.2.6 | Computer tomography methods for small gears | 21 |
| 6.2.7 | Optical devices for small spur gears | 21 |
| 6.3 | Calibration of equipment | 22 |
| 6.4 | Tooth thickness, differences between CNC/CMM and manual measurement | 22 |
| 6.5 | "In-process" gear measurement on manufacturing machines | 23 |
| 6.6 | Gear mounting | 23 |
| 6.7 | Example output format from a CNC GMM | 24 |
| 6.7.1 | General | 24 |
| 6.7.2 | Example evaluations of modified helices and profiles | 27 |
| 7 | Recommended measurement procedure and good measurement practice | 28 |
| 7.1 | Measurement procedure | 28 |
| 7.2 | Probe problems when measuring aluminium parts | 30 |
| 7.3 | Suitable artefacts for calibration of measuring machines | 30 |
| 8 | Inspection procedures for gears that are too large for gear inspection machines | 31 |
| 8.1 | General | 31 |
| 8.2 | Profile inspection using portable device | 31 |
| 8.2.1 | Disassembly of segments | 31 |

| | | |
|---------|---|----|
| 8.2.2 | Measurement by portable gear inspection device using coordinates | 31 |
| 8.2.3 | Profile inspection by gear tooth caliper | 32 |
| 8.3 | Inspection of helix form deviation | 36 |
| 8.3.1 | Inspection of helix form deviation on the gear cutting machine | 36 |
| 8.3.2 | Straightness inspection using a cylinder | 37 |
| 8.3.3 | Inspection of the tooth contact pattern | 37 |
| 8.4 | Inspection of the pitch | 38 |
| 8.4.1 | Calculation of pitch | 38 |
| 8.4.2 | Inspection using an automatic device on the cutting machine: inspection of the single circular pitch and the cumulative pitch deviation | 38 |
| 8.4.3 | Manual inspection: inspection of base pitch, pb, and base pitch deviations, fpb | 39 |
| 8.5 | Measuring tooth thickness | 39 |
| 8.6 | Measuring gear radial runout and axial runout of reference surfaces | 39 |
| 9 | Measurement analysis -- Profile, helix, pitch and radial runout | 39 |
| 9.1 | Profile | 39 |
| 9.1.1 | Profile deviation | 39 |
| 9.1.2 | Profile deviation diagram | 40 |
| 9.1.3 | Evaluation of profile diagrams | 41 |
| 9.1.4 | Algebraic signs of fH, fb and f | 42 |
| 9.1.5 | Mean profile slope deviation, fHm | 42 |
| 9.2 | Helix | 43 |
| 9.2.1 | General | 43 |
| 9.2.2 | Helix deviation diagram | 44 |
| 9.2.3 | Evaluation of helix diagrams | 45 |
| 9.2.4 | Algebraic signs of fH and f | 46 |
| 9.2.5 | Machine corrections based on mean helix slope deviation, fHm | 47 |
| 9.3 | Pitch | 48 |
| 9.3.1 | Pitch deviation | 48 |
| 9.3.2 | Pitch deviation measurement | 48 |
| 9.3.3 | Relationships of pitch parameters and measuring methods | 48 |
| 9.3.4 | Calculation of cumulative pitch (index), Fp | 49 |
| 9.3.5 | Calculation of single pitch, fpi | 50 |
| 9.3.6 | Calculation of total cumulative pitch deviation, Fp | 50 |
| 9.3.7 | Calculation of sector pitch deviation, Fpk | 50 |
| 9.3.8 | Segment gear measurement | 50 |
| 9.4 | Radial runout, determining eccentricity | 51 |
| 9.4.1 | Measuring principle | 51 |
| 9.4.2 | Evaluation of measurement | 51 |
| 10 | Interpretation of profile, helix, pitch and radial runout results | 52 |
| 10.1 | Interpreting measurement results | 52 |
| 10.2 | Procedure for interpreting measurement results | 52 |
| 10.3 | Recognition of common manufacturing errors | 53 |
| 10.3.1 | General | 53 |
| 10.3.2 | Example of a profile with pressure angle deviation | 53 |
| 10.3.3 | Example of profile deviations with varying pressure angle deviation | 53 |
| 10.3.4 | Hob runout or shaping cutter deflection | 54 |
| 10.3.5 | Consistent mean helix slope deviation | 55 |
| 10.3.6 | Helix slope variation | 55 |
| 10.3.7 | Profile control diameter not achieved | 56 |
| 10.3.8 | Variation in profile non-clean up and profile control diameter not achieved | 56 |
| 10.3.9 | Pitch results with radial runout of the gear blank | 58 |
| 10.3.10 | Pitch with indexing deviations | 58 |
| 10.3.11 | Pitch with repeating deviation patterns that may cause noise | 61 |
| 11 | Single flank composite testing | 61 |
| 11.1 | Single flank composite testing principle | 61 |
| 11.2 | Single flank composite test | 62 |
| 11.2.1 | Single flank test setup | 62 |
| 11.2.2 | Single flank composite deviations | 64 |

| | | |
|--------|---|----|
| 11.3 | Single flank measurement with master gear | 65 |
| 11.3.1 | Master gear requirements | 65 |
| 11.3.2 | Influence of profile deviations | 65 |
| 11.3.3 | Influence of pitch deviations | 66 |
| 11.3.4 | Influence of helix deviations | 66 |
| 11.4 | Single flank measurement of product gear pair | 69 |
| 11.4.1 | Differences between tests with a master gear and between two product gears | 69 |
| 11.4.2 | Identification and location of defects | 69 |
| 11.4.3 | Selective meshing of gears | 69 |
| 11.5 | Data analysis by the Fourier transform method | 70 |
| 12 | Additional measurements | 71 |
| 12.1 | Flank measurements | 71 |
| 12.1.1 | General | 71 |
| 12.1.2 | Twist measurement | 71 |
| 12.1.3 | Topographical measurement | 72 |
| 12.1.4 | Undulations | 73 |
| 12.2 | Surface roughness measurement | 74 |
| 12.3 | Tooth root fillet radius measurement | 74 |
| 13 | Filters and data density | 75 |
| 13.1 | General | 75 |
| 13.2 | Examples of filtered results | 75 |
| 13.3 | Working principle of the Gauss 50 % filter | 75 |
| 13.4 | Filter limitations | 81 |
| 14 | Additional calculations | 81 |
| 14.1 | Calculation of single pitch deviation, f_{pt} , from normal base pitch measurements | 81 |
| 14.2 | Additional calculations for normal base pitch measurements | 82 |
| 14.2.1 | Included parameters | 82 |
| 14.2.2 | Calculation of normal base pitch deviation, f_{pbn} | 82 |
| 14.2.3 | Calculation of mean normal base pitch deviation, f_{pbnm} | 82 |
| 14.3 | Additional calculations for profile measurements | 82 |
| 14.3.1 | Included parameters | 82 |
| 14.3.2 | Mean base diameter deviation and mean pressure angle deviation | 83 |
| 14.3.3 | Calculation of effective base diameter, $d_{b\text{ eff}}$ | 84 |
| 14.3.4 | Calculation of effective transverse pressure angle, $t_{\text{ eff}}$ | 84 |
| 14.3.5 | Calculation of effective normal pressure angle, $n_{\text{ eff}}$ | 84 |
| 14.3.6 | Calculation of mean transverse pressure angle deviation, f_{mt} | 85 |
| 14.3.7 | Calculation of mean normal pressure angle deviation, f_{mn} | 85 |
| 14.4 | Additional calculations for helix measurements | 85 |
| 14.4.1 | Included parameters | 85 |
| 14.4.2 | Required preliminary data | 86 |
| 14.4.3 | Calculation of effective helix angle at the measurement diameter, $M_{\text{ eff}}$ | 86 |
| 14.4.4 | Calculation of effective lead, $p_{z\text{ eff}}$ | 86 |
| 14.4.5 | Calculation of effective helix angle at the standard pitch diameter, eff | 87 |
| 14.4.6 | Calculation of mean lead deviation, f_{pzm} | 87 |
| 14.4.7 | Calculation of mean helix angle deviation, f_m | 87 |
| | Bibliography | 89 |