

ISO 19685:2017-09 (E)

Vacuum technology - Vacuum gauges - Specifications, calibration and measurement uncertainties for Pirani gauges

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	4
5	Principle of Pirani gauge	4
6	Specifications for Pirani gauge	5
6.1	General	5
6.2	Measuring principle	5
6.3	Type of output	5
6.4	Range of output and output display resolution	5
6.5	Measurement range and full scale	5
6.6	Expected measurement uncertainty	5
6.7	Material exposed to gas	5
6.8	Connecting flange	5
6.9	Interface and pin-connections	6
6.10	Warm-up period	6
6.11	Compatibility between gauge tube and controller	6
6.12	Normal operating (environment) conditions	6
6.13	Electrical power supply	6
6.14	Cable length	6
6.15	Maximum bake-out temperature	6
6.16	Dimensions of gauge head and controller	6
6.17	Mounting orientation	6
7	Additional (optional) specifications for Pirani gauge	6
7.1	Long-term instability	6
7.2	Relative sensitivity factor	7
7.3	Hysteresis	7
7.4	Response time	7
7.5	Inspection record and calibration certificate	7
7.6	Configuration	7
7.7	Weight	7
7.8	Storage and transport condition	7
7.9	Photographs	7
7.10	Maximum power consumption	7
7.11	Set point of pressure	7
8	Calibration and other measurement procedures	7
8.1	General	7
8.2	Conditions for calibrations	8
8.3	Assembly and adjustments of calibration item	8
8.4	Calibration	9

8.5	Measurement uncertainties during calibration	9
8.6	Calibration certificate	9
8.7	Measurement procedure for hysteresis	10
8.8	Measurement procedure of response time	10
9	Measurement uncertainties at use	10
Annex A (informative) Typical Pirani gauge		12
Bibliography		13