

ISO 19085-6:2017-11 (E)

Woodworking machines - Safety - Part 6: Single spindle vertical moulding machines ("toupies")

Contents		Page
Foreword		vi
Introduction		vii
1	Scope	1
2	Normative references	2
3	Terms and definitions	2
4	List of significant hazards	8
5	Safety requirements and measures for controls	10
5.1	Safety and reliability of control systems	10
5.2	Control devices	10
5.3	Start	11
5.4	Safe stops	11
5.4.1	General	11
5.4.2	Normal stop	11
5.4.3	Operational stop	11
5.4.4	Emergency stop	11
5.5	Braking function of tool spindles	12
5.6	Mode selection	12
5.7	Spindle speed changing	12
5.7.1	Spindle speed changing by changing belts on the pulleys	12
5.7.2	Spindle speed changing by incremental speed change motor	12
5.7.3	Infinitely variable speed by frequency inverter	12
5.7.4	Spindle speed limiting device for tenoning	12
5.7.5	Changing of the direction of spindle rotation	12
5.8	Failure of any power supply	13
5.9	Manual reset control	13
5.10	Enabling control	13
5.11	Machine moving parts speed monitoring	13
5.12	Time delay	14
5.13	Power driven adjustment of arbor, demountable power feed unit, fences and table insert	14
6	Safety requirements and measures for protection against mechanical hazards	14
6.1	Stability	14
6.1.1	Stationary machines	14
6.1.2	Displaceable machines	14
6.2	Risk of break-up during operation	15
6.3	Tool holder and tool design	15
6.3.1	General	15
6.3.2	Spindle locking	17
6.3.3	Circular saw blade fixing device	18
6.3.4	Flange dimension for circular saw blades	18
6.3.5	Arbor rings	18
6.3.6	Quick tool/arbor change system	18
6.3.7	Manual adjustment of arbor height	18
6.3.8	Manual adjustment of arbor inclination	19
6.4	Braking	19

6.4.1	Braking of tool spindles	19
6.4.2	Maximum run-down time	19
6.4.3	Brake release	20
6.5	Safeguards	20
6.5.1	Fixed guards	20
6.5.2	Interlocking movable guards	20
6.5.3	Hold-to-run control	20
6.5.4	Two-hand control	20
6.5.5	Electro-sensitive protective equipment (ESPE)	20
6.5.6	Pressure-sensitive protective equipment (PSPE)	20
6.6	Prevention of access to moving parts	20
6.6.1	General	20
6.6.2	Guarding of tools	20
6.6.3	Guarding of drives	24
6.6.4	Guarding of shearing and/or crushing zones	24
6.7	Impact hazard	24
6.8	Clamping devices	24
6.9	Measures against ejection	25
6.9.1	General	25
6.9.2	Guards materials and characteristics	25
6.9.3	Anti-kickback devices	25
6.10	Work-piece supports and guides	27
6.10.1	Table	27
6.10.2	Work-piece guiding for straight work	30
6.10.3	Work-piece guiding for curved work	30
6.11	Safety appliances	31
7	Safety requirements and measures for protection against other hazards	32
7.1	Fire	32
7.2	Noise	32
7.2.1	Noise reduction at the design stage	32
7.2.2	Noise emission measurement	32
7.3	Emission of chips and dust	32
7.4	Electricity	33
7.4.1	General	33
7.4.2	Displaceable machines	33
7.5	Ergonomics and handling	33
7.6	Lighting	33
7.7	Pneumatics	33
7.8	Hydraulics	33
7.9	Electromagnetic compatibility	33
7.10	Laser	34
7.11	Static electricity	34
7.12	Errors of fitting	34
7.13	Isolation	34
7.14	Maintenance	34
8	Information for use	34
8.1	Warning devices	34
8.2	Marking	34
8.2.1	General	34
8.2.2	Additional markings	34
8.3	Instruction handbook	34
8.3.1	General	34
8.3.2	Additional information	34
	Annex A (informative) Performance level required	38
	Annex B (normative) Test for braking function	40
	Annex C (normative) Stability test for displaceable machines	41

Annex D (normative) Impact test for guards42
Annex E (normative) Noise emission measurement for machines not in ISO 7960:199543
Annex F (informative) Determination of maximum spindle speeds for single piece arbors44
Annex G (normative) Rigidity test for pressure pads, hand protectors and guiding steadies48
Bibliography53