

ISO 19085-13:2020-05 (E)

Woodworking machines - Safety - Part 13: Multi-blade rip sawing machines with manual loading and/or unloading

Contents

Page

Foreword.....	v
Introduction.....	vi
1 Scope.....	1
2 Normative references.....	1
3 Terms and definitions.....	2
4 List of significant hazards.....	4
5 Safety requirements and measures for controls.....	6
5.1 Safety and reliability of control systems.....	6
5.2 Control devices.....	6
5.3 Start.....	8
5.4 Safe stops.....	8
5.4.1 General.....	8
5.4.2 Normal stop.....	8
5.4.3 Operational stop.....	8
5.4.4 Emergency stop.....	8
5.5 Braking function of tool spindles.....	8
5.6 Mode selection.....	8
5.6.1 General.....	8
5.6.2 Pressure shoe/board cutting mode.....	8
5.6.3 Cleaning mode.....	9
5.6.4 Powered axial adjustment mode.....	9
5.7 Spindle speed changing.....	10
5.7.1 Spindle speed changing by changing belts on the pulleys.....	10
5.7.2 Spindle speed changing by incremental speed change motor.....	10
5.7.3 Infinitely variable speed by frequency inverter.....	10
5.8 Failure of any power supply.....	10
5.9 Manual reset control.....	10
5.10 Enabling control.....	10
5.11 Machine moving parts limited speed monitoring.....	10
5.12 Time delay.....	10
5.13 Powered adjustments when guards are closed.....	10
6 Safety requirements and measures for protection against mechanical hazards.....	11
6.1 Stability.....	11
6.1.1 Stationary machines.....	11
6.1.2 Displaceable machines.....	11
6.2 Risk of break-up during operation.....	11
6.3 Tool holder and tool design.....	11
6.3.1 General.....	11
6.3.2 Spindle locking.....	11
6.3.3 Circular saw blade fixing device.....	11
6.3.4 Flanges dimensions for circular saw blades.....	11
6.4 Braking.....	11
6.4.1 Braking of tool spindles.....	11
6.4.2 Maximum run-down time.....	12
6.4.3 Brake release.....	12
6.5 Safeguard design.....	12
6.5.1 Fixed guards.....	12

6.5.2	Interlocking moveable guards.....	12
6.5.3	Hold-to-run control.....	12
6.5.4	Two-hand control.....	12
6.5.5	Electro-sensitive protective equipment (ESPE).....	12
6.5.6	Pressure sensitive protective equipment (PSPE).....	12
6.6	Prevention of access to moving parts.....	12
6.6.1	General.....	12
6.6.2	Guarding of tools.....	13
6.6.3	Guarding of drives.....	13
6.6.4	Guarding of crushing and shearing zones.....	13
6.7	Impact hazard.....	14
6.8	Clamping devices.....	14
6.9	Measures against ejection.....	14
6.9.1	General.....	14
6.9.2	Guards materials and characteristics.....	14
6.9.3	Measures against ejection through the infeed opening.....	15
6.9.4	Measures against ejection through the outfeed opening.....	25
6.10	Work-piece support and guide.....	28
7	Safety requirements and measures for protection against other hazards.....	28
7.1	Fire.....	28
7.2	Noise.....	28
7.2.1	Noise reduction at the design stage.....	28
7.2.2	Noise emission measurement.....	28
7.3	Emission of chips and dust.....	28
7.4	Electricity.....	28
7.4.1	General.....	28
7.4.2	Displaceable machines.....	28
7.5	Ergonomics and handling.....	28
7.6	Lighting.....	28
7.7	Pneumatics.....	29
7.8	Hydraulics.....	29
7.9	Electromagnetic compatibility.....	29
7.10	Laser.....	29
7.11	Static electricity.....	29
7.12	Errors of fitting.....	29
7.13	Isolation.....	29
7.14	Maintenance.....	29
8	Information for use.....	29
8.1	Warning devices.....	29
8.2	Marking.....	29
8.2.1	General.....	29
8.2.2	Additional marking.....	29
8.3	Instruction handbook.....	30
8.3.1	General.....	30
8.3.2	Additional information.....	30
	Annex A (informative) Performance level required.....	31
	Annex B (normative) Test for braking function.....	32
	Annex C (normative) Stability test for displaceable machines.....	33
	Annex D (normative) Impact test method for guards.....	34
	Annex E (normative) Noise emission measurement for machines not in ISO 7960:1995.....	35
	Annex F (normative) Test for the anti-splinter system on machines with one chain conveyor.....	36
	Bibliography.....	40

Annex F (normative) Test for the anti-splinter system on machines with one chain conveyor36
Bibliography40