

DIN EN 1822-4:2001-02 (E)

High efficiency particulate air filters (HEPA and ULPA) - Part 4: Determining leakage of filter elements (Scan method); English version of DIN EN 1822-4

Contents

	Page
Foreword	3
Introduction	3
1 Scope	4
2 Normative references	4
3 Terms and definitions.....	4
3.1 sampling volume flow rate	4
3.2 sampling duration	5
3.3 total particle count method	5
3.4 particle counting and sizing method.....	5
3.5 particle flow rate	5
3.6 particle flow distribution.....	5
4 Description of the procedure	5
5 Test filter	6
6 Test apparatus.....	7
6.1 Set-up of the test apparatus.....	7
6.2 Test duct.....	9
6.3 Scanning assembly.....	10
6.4 Aerosol generation and measurement techniques.....	11
7 Test air	13
8 Test procedure	13
8.1 General	13
8.2 Preparatory checks	14
8.3 Starting up the aerosol generator	14
8.4 Preparing the test filter.....	15
8.5 Testing	15
9 Evaluation.....	17
9.1 Calculating the penetration and the efficiency.....	17
9.2 Local penetration.....	19
9.3 Mean efficiency	19
9.4 Classification.....	19
10 Test report.....	19
10.1 Details of the test filter	19
10.2 General details of the test parameters	19
10.3 Test results.....	20
11 Maintenance and inspection of the test apparatus	20
Annex A (normative) Oil thread test	22
Annex B (normative) Determining the test parameters	23
Annex C (informative) Example of an application with evaluation	33
Bibliography	35