

DIN EN ISO 23063:2026-08 (E)

Foundry machinery - Safety requirements for high pressure die casting machines (ISO 23063:2024)

Contents

Page

Foreword.....	v
Introduction.....	vi
1 Scope.....	1
2 Normative references.....	1
3 Terms and definitions.....	3
4 List of significant hazards.....	7
4.1 General.....	7
4.2 Mechanical hazards.....	7
4.3 Electrical and control system hazards.....	7
4.3.1 Electrical hazards.....	7
4.3.2 Control system hazards.....	7
4.4 Thermal hazards.....	8
4.5 Fire hazards.....	8
4.6 Noise hazards.....	8
4.7 Hazards caused by gases, vapours, fumes and dusts.....	8
4.8 Hazards generated by neglecting ergonomic principles in machinery design.....	8
4.9 Hazards during the setting mode.....	9
4.10 Falls from heights.....	9
4.11 Hazards related to cold-chamber die casting machines.....	9
4.11.1 Bursting of biscuits.....	9
4.11.2 Injection drive area.....	9
4.12 Hazards related to hot-chamber die casting machines.....	9
4.12.1 Nozzle.....	9
4.12.2 Initiation of the casting process due to a fault in the control system.....	9
4.13 Hazards due to hydraulics and pneumatics.....	9
5 Safety requirements and/or protective measures.....	10
5.1 General.....	10
5.2 Mechanical.....	10
5.2.1 General.....	10
5.2.2 Guards and protective devices for the die area.....	10
5.2.3 Access to the die closing mechanism area.....	12
5.2.4 Additional requirements for movable guards and access doors.....	12
5.2.5 Die casting units.....	13
5.3 Electric equipment and control systems.....	14
5.3.1 Electric equipment.....	14
5.3.2 Safety related parts of the control system: General.....	14
5.3.3 Emergency stop functions.....	14
5.3.4 Safety related control system of the dangerous movements of the die.....	14
5.3.5 Control of ancillary equipment.....	15
5.4 Measures against thermal hazards.....	16
5.4.1 Spurting of molten metal.....	16
5.4.2 Contact with hot surfaces.....	16
5.5 Hydraulics, pneumatics and combustible fluids.....	16
5.5.1 Hydraulics, pneumatics.....	16
5.5.2 Pressure fluids.....	16
5.5.3 Spray systems for release agents.....	16
5.6 Noise.....	17

5.6.1	Noise reduction as a safety requirement.....	17
5.6.2	Noise emission measurement and declaration on die casting machines.....	17
5.6.3	Noise test code.....	17
5.7	Gases, vapours, fumes and dusts.....	19
5.8	Ergonomic aspects.....	19
5.9	Protective measures when setting-up of die casting machines, inserting and removing appliances, tie bar pulling devices and other ancillary equipment.....	19
5.9.1	Setting-up without protective devices for the die area.....	19
5.9.2	Movement of core pullers and ejectors.....	20
5.9.3	Movement of tie bars.....	20
5.9.4	Movement of the plunger of cold-chamber machines.....	20
5.10	Elevated working places.....	20
5.11	Additional protective measures for cold-chamber die casting machines.....	21
5.11.1	Bursting and removal of biscuit.....	21
5.11.2	Guards and protective devices for the injection area.....	21
5.12	Additional protective measures for hot-chamber die casting machines.....	21
5.12.1	Metal splashing.....	21
5.12.2	Movement of the injection piston.....	21
6	Verification of the safety requirements and/or protective measures.....	22
7	Information for use.....	23
7.1	General.....	23
7.2	Warning devices and safety signs.....	23
7.3	Accompanying documents.....	23
7.3.1	Instruction handbook.....	23
7.4	Marking.....	25
	Annex A (informative) Examples.....	27
	Annex B (normative) Requirements for the European Union and associated countries.....	40
	Annex C (normative) Requirements for China (noise test code).....	41
	Bibliography.....	42