

Contents	Page
Foreword	vi
Introduction	vii
1 Scope	1
2 Normative References	1
3 Terms and definitions	1
4 Overview and warnings	1
4.1 Overview.....	1
4.2 Warnings.....	2
5 Tribological damage (non-fatigue)	2
5.1 General.....	2
5.2 Polishing.....	2
5.2.1 General.....	2
5.2.2 Summary of methods that have been observed to reduce the risk of polishing.....	3
5.3 Scratches.....	3
5.4 Abrasive wear.....	3
5.4.1 General.....	3
5.4.2 Sources of particles that cause abrasive wear.....	3
5.4.3 Methods for reducing abrasive wear.....	4
5.5 Scuffing.....	5
5.5.1 General.....	5
5.5.2 Methods for reducing the risk of scuffing.....	6
5.5.3 Summary of methods that have been observed to reduce the risk of scuffing.....	7
5.6 Adhesive wear (Adhesion).....	8
5.6.1 General.....	8
5.6.2 Summary of methods that have been observed to reduce the risk of adhesive wear.....	9
5.7 Fretting corrosion.....	9
5.7.1 General.....	9
5.7.2 False brinelling.....	9
5.7.3 Fretting corrosion.....	10
5.7.4 Summary of methods that have been observed to reduce the risk of fretting.....	10
5.8 Interference wear.....	11
6 Fatigue damage	11
6.1 Fatigue cracks.....	11
6.2 Contact fatigue.....	11
6.2.1 General.....	11
6.2.2 Micropitting.....	11
6.2.3 Macropitting.....	15
6.2.4 Case crushing (subcase fatigue).....	19
6.2.5 White layer flaking.....	20
6.2.6 Tooth flank fracture (TFF) (subsurface initiated bending fatigue).....	20
6.2.7 Tooth interior fatigue fracture, TIFF.....	21
6.3 Bending fatigue.....	22
6.3.1 Tooth root fatigue fracture.....	22
6.3.2 Rim web and hub cracks.....	28
7 Non-fatigue fracture	29
7.1 General.....	29
7.1.1 Brittle fracture.....	29
7.1.2 Summary of methods that have been observed to reduce the risk of brittle fracture.....	30
7.1.3 Ductile fracture.....	31

	7.1.4	Mixed mode fracture	31
	7.2	Tooth root rupture	31
	7.3	Tooth end rupture	31
	7.4	Tooth shear fracture	32
8		Plastic Deformation	32
	8.1	General	32
	8.2	Indentation	32
	8.3	Brinelling	32
	8.4	Cold flow	32
	8.5	Hot flow	33
	8.6	Root fillet yielding	33
	8.7	Fracture after plastic deformation	33
	8.8	Rolling	33
	8.9	Tooth hammer	33
	8.10	Rippling	33
	8.11	Ridging	33
	8.12	Burr	33
	8.13	Interference deformation	34
	8.13.1	Tip to root fillet interference	34
	8.13.2	Tip-to-dedendum interference	34
	8.13.3	Tight mesh	34
9		Manufacturing problems	34
	9.1	Forging cracks	34
	9.2	Hardening cracks	34
	9.2.1	General	34
	9.2.2	Thermal stresses	34
	9.2.3	Stress concentration due to heat treatment	35
	9.2.4	Quench severity	35
	9.2.5	Phase transformation	35
	9.2.6	Material defects	35
	9.2.7	Heat treating practice	35
	9.2.8	Tempering practice	36
	9.2.9	Detection of hardening cracks	36
	9.2.10	Summary of methods that have been observed to reduce the risk of hardening cracks	36
	9.3	Grinding cracks	36
	9.3.1	General	36
	9.3.2	Summary of methods that have been observed to reduce the risk of grinding cracks	37
	9.4	Hydrogen and internal residual stress gear failures	37
	9.4.1	General	37
	9.4.2	Hydrogen flake term	38
	9.4.3	Fish eye	39
	9.4.4	Segregation cracks	39
	9.4.5	Deferred breakage	40
	9.5	Grinding burn (temper due to grinding)	40
	9.6	Grinding notch	40
	9.7	Scaling	40
	9.8	Case/core separation	40
	9.8.1	General	40
	9.8.2	Summary of methods that have been observed to reduce the risk of case/ core separation	41
10		Other surface damage	41
	10.1	Corrosion	41
	10.1.1	General	41
	10.1.2	Summary of methods that have been observed to reduce the risk of corrosion	42

10.2	Cavitation.....	42
10.3	Erosion.....	43
10.4	Electric discharge.....	43
	10.4.1 General.....	43
	10.4.2 Summary of methods that have been observed to reduce the risk of electrical discharge damage.....	43
10.5	Overheating.....	44
Bibliography	45