

# ISO 23582-1:2023-03 (E)

## Plastics and rubber machines - Clamping systems - Part 1: Safety requirements for magnetic clamping systems

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Safety requirements and/or protective/risk reduction measures .....</b>	<b>3</b>
4.1	General .....	3
4.2	Magnets .....	3
4.3	Magnetic plate(s) .....	3
4.4	Magnetizing/demagnetizing current .....	3
4.5	Magnetic clamping control system .....	3
4.5.1	Magnetic clamping control system detection requirements .....	3
4.5.2	Magnetic clamping control system magnetizing/demagnetizing .....	3
4.5.3	Magnetic clamping control system enabling machine movements .....	4
4.6	Magnetic clamping system force .....	4
4.6.1	General .....	4
4.6.2	Magnetic clamping system force when the MCS is integrated in horizontal machines .....	4
4.6.3	Magnetic clamping system force when the MCS is integrated in vertical machines .....	4
4.7	Electrical hazards and hazards due to electromagnetic interference .....	5
4.7.1	General .....	5
4.7.2	Basic protection .....	5
4.7.3	Fault protection .....	5
4.7.4	Protection against ingress of solids and liquids .....	5
4.7.5	Protection against electromagnetic interference .....	5
<b>5</b>	<b>Verification of safety requirements and/or protective/risk reduction measures .....</b>	<b>5</b>
<b>6</b>	<b>Information for the integration and the use of the MCS .....</b>	<b>6</b>
6.1	Instruction for the integration of the MCS in a plastics and rubber machine .....	6
6.1.1	General .....	6
6.1.2	Forces acting against the magnetic clamping system force .....	6
6.1.3	Machine movements .....	7
6.1.4	Signals from the machine to the MCS .....	7
6.2	Instruction for the use of an MCS in a plastics and rubber machine .....	7
<b>7</b>	<b>Marking .....</b>	<b>8</b>
<b>Annex A (informative)</b>	<b>List of significant hazards .....</b>	<b>9</b>
<b>Annex B (informative)</b>	<b>Cantilever effect for half mould in horizontal machine .....</b>	<b>11</b>