

# DIN 5480-15:2006-03 (E)

## Involute splines based on reference diameters - Part 15: Inspection

---

<b>Contents</b>		<b>Page</b>
Foreword .....		4
<b>1</b>	<b>Scope .....</b>	<b>5</b>
<b>2</b>	<b>Normative references .....</b>	<b>5</b>
<b>3</b>	<b>Definitions and symbols, designations and units .....</b>	<b>5</b>
3.1	Definitions .....	5
3.1.1	space width/tooth thickness .....	5
3.1.2	Terms relating to inspection of the actual space width/tooth thickness .....	6
3.1.3	Terms describing the centre points of the tooth flanks .....	7
3.1.4	Individual deviations .....	7
3.2	Symbols, designations and units .....	8
<b>4</b>	<b>Parameters to be inspected .....</b>	<b>9</b>
4.1	General .....	9
4.2	Dimensions .....	10
4.2.1	Diameters .....	10
4.2.2	Space width/tooth thickness .....	10
4.3	Individual deviations .....	14
4.4	Positional deviations .....	14
<b>5</b>	<b>Inspection procedure .....</b>	<b>15</b>
5.1	General .....	15
5.1.1	Inspection of the actual space width/actual tooth thickness .....	15
5.1.2	Inspection of the effective space width/effective tooth thickness .....	15
5.1.3	Checking individual deviations .....	16
5.1.4	Positional deviations .....	16
5.2	Gauges .....	16
5.2.1	Types of gauge and their uses .....	16
5.2.2	External dimensions .....	17
5.2.3	Materials, surface finish and design .....	19
5.2.4	Inspection dimensions, tolerances and limit deviations .....	20
5.2.5	Gauge inspection .....	25
5.3	Inspection of space width/tooth thickness using indicating measuring instruments .....	30
5.3.1	General .....	30
5.3.2	Dimension between/over measuring circles .....	30
5.3.3	Base tangent length .....	32
5.3.4	Measurement uncertainty .....	32
5.3.5	Rules of priority .....	33
5.3.6	Statistical actual tolerance limit (STA) .....	33
5.4	Inspection of the effective space width/effective tooth thickness .....	34
5.4.1	Inspection taking individual deviations into account .....	34
5.4.2	Checking the rotational flank backlash .....	34
5.5	Checking individual deviations .....	35
5.5.1	Comparability with transmission gear splines .....	35
5.5.2	Effect of positional deviations on measurements .....	35
5.6	Checking positional deviations .....	35
5.6.1	Representation in workpiece drawings .....	35
5.6.2	Effect of individual deviations on measurements and inspection results .....	35
5.6.3	Actual positional deviations .....	35
5.6.4	Effective positional deviations .....	36

<b>Annex A (informative) Comparison of new symbols and old symbols .....</b>	<b>37</b>
<b>Bibliography .....</b>	<b>38</b>
<b>Figures</b>	
<b>Figure 1 -- Parameters to be inspected .....</b>	<b>9</b>
<b>Figure 2 -- Diameters .....</b>	<b>10</b>
<b>Figure 3 -- Space widths and tooth thicknesses .....</b>	<b>11</b>
<b>Figure 4 -- Spline envelope .....</b>	<b>12</b>
<b>Figure 5 -- Actual reference mark and actual existing dimension .....</b>	<b>14</b>
<b>Figure 6 -- Actual and effective positional deviations .....</b>	<b>15</b>
<b>Figure 7 -- Plug gauge (sizes 1 to 6) .....</b>	<b>17</b>
<b>Figure 8 -- Plug gauge (sizes 7 to 9) .....</b>	<b>18</b>
<b>Figure 9 -- Ring gauge .....</b>	<b>19</b>
<b>Figure 10 -- Diagram showing gauge tolerances .....</b>	<b>21</b>
<b>Figure 11 -- Relieved flanks in NO GO gauges .....</b>	<b>23</b>
<b>Figure 12 -- Dimensions over and between measuring circles .....</b>	<b>23</b>
<b>Figure 13 -- Radial runout of gauges .....</b>	<b>25</b>
<b>Figure 14 -- Master plug gauge with teeth tapered on one side .....</b>	<b>27</b>
<b>Figure 15 -- NO GO gauges .....</b>	<b>28</b>
<b>Figure 16 -- Composite master gauges .....</b>	<b>32</b>
<b>Figure 17 -- Statistical actual tolerance limit STA .....</b>	<b>33</b>
<b>Tables</b>	
<b>Table 1 -- Number of teeth for sector NO GO gauges .....</b>	<b>16</b>
<b>Table 2 -- Length of the measuring part of plug gauges .....</b>	<b>17</b>
<b>Table 3 -- External dimensions of plug gauges of sizes 7 to 9 .....</b>	<b>18</b>
<b>Table 4 -- External dimensions, ring gauges .....</b>	<b>19</b>
<b>Table 5 -- Gauge diameters .....</b>	<b>20</b>
<b>Table 6 -- Tooth thickness/space width for gauges .....</b>	<b>20</b>
<b>Table 7 -- Gauge manufacturing tolerances .....</b>	<b>22</b>
<b>Table 8 -- Total helix deviations of gauges .....</b>	<b>22</b>
<b>Table 9 -- Calculating measurements between/over measuring circles .....</b>	<b>24</b>
<b>Table 10 -- Spline gauge features to be inspected .....</b>	<b>26</b>
<b>Table 11 -- Data field for workpiece to be inspected .....</b>	<b>29</b>
<b>Table 12 -- Spline gauge data field in drawings .....</b>	<b>29</b>
<b>Table 13 -- Tolerances for measuring circle diameters (of balls or pins) .....</b>	<b>30</b>