

# DIN 6868-161:2013-01 (E)

## Image quality assurance in diagnostic X-ray departments - Part 161: RöV acceptance testing of dental radiographic equipment for digital cone-beam computed tomography

---

<b>Contents</b>	<b>Page</b>
Foreword .....	4
1 Scope .....	6
2 Normative references .....	6
3 Terms and definitions .....	6
4 Performance of the ACCEPTANCE TEST .....	7
4.1 General .....	7
4.2 TEST PHANTOM .....	8
4.3 Test items .....	10
4.3.1 Visual inspection and functional tests .....	10
4.3.2 Alignment of the RADIATION FIELD and the active detector area .....	11
4.3.3 Reproducibility of the dose .....	11
4.3.4 Spatial resolution of the reconstruction .....	11
4.3.5 Spatial resolution .....	12
4.3.6 ACCEPTANCE INDEX .....	12
4.3.7 HOMOGENEITY INDEX .....	14
4.3.8 ARTEFACTS .....	15
Annex A (normative) Simplified determination of the MODULATION TRANSFER BEHAVIOUR .....	16
Annex B (normative) Calculation of the CONTRAST-TO-NOISE INDEX .....	18
Annex C (informative) Possible ARTEFACTS in DENTAL DIGITAL CONE-BEAM COMPUTED TOMOGRAPHY (CBCT) .....	20
C.1 General .....	20
C.2 Beam-hardening ARTEFACTS .....	20
C.3 Extinction ARTEFACTS .....	21
C.4 Partial volume effect and exponential-edge-gradient effect (EEGE) .....	22
C.5 Aliasing ARTEFACTS .....	22
C.6 Ring ARTEFACTS .....	23
C.7 ARTEFACTS caused by geometrical errors (e.g., motion ARTEFACTS) .....	24
Annex D (informative) Dose measurement in DENTAL DIGITAL CONE-BEAM COMPUTED TOMOGRAPHY (CBCT) -- Differences from computed tomography .....	25
D.1 Background .....	25
D.2 Prerequisites for the measurement of dose in DENTAL CBCT .....	25
D.2.1 Imaged volume .....	25
D.2.2 Scan geometry .....	25
D.2.3 Measurement devices .....	26
D.3 Summary .....	26
Annex E (informative) Figures .....	27
E.1 MODULATION TRANSFER BEHAVIOUR .....	28

E.2	Scan geometry .....	28
E.3	HOMOGENEITY .....	29
Bibliography .....		30
Keyword index .....		32
Figures	Figure 1 -- Set-up and alignment of the TEST PHANTOM in the beam path .....	8
	Figure 2 -- Homogeneous elements of the TEST PHANTOM .....	9
	Figure 3 -- Structure elements of the TEST PHANTOM; top view and cross-sectional view .....	10
	Figure C.1 -- Typical striped beam-hardening ARTEFACTS in the direction of the beam path, caused by metal implants (titanium) in DENTAL CBCT .....	21
	Figure C.2 -- Extinction ARTEFACTS in the direction of the beam path due to very dense gold restorations in the teeth .....	21
	Figure C.3 -- Intensity errors .....	22
	Figure C.4 -- Subtle line patterns (Moiré patterns) .....	23
	Figure C.5 -- Ring ARTEFACTS .....	23
	Figure C.6 -- Typical motion ARTEFACTS that manifest themselves as double contours .....	24
	Figure E.1 -- Example of the positioning and borders of the region of interest (ROI) used to determine the MODULATION TRANSFER BEHAVIOUR .....	27
	Figure E.2 -- Example of the graphical presentation of the MODULATION TRANSFER BEHAVIOUR .	28
	Figure E.3 -- Horizontal slice through a scan geometry (Example 1) .....	28
	Figure E.4 -- Horizontal slice through a scan geometry (Example 2) .....	29
	Figure E.5 -- Example for the position and borders of the fields for the determination of HOMOGENEITY .....	29