

ISO 4037-3:1999-06 (E)

X and gamma reference radiation for calibrating dosimeters and doserate meters and for determining their response as a function of photon energy - Part 3:
Calibration of area and personal dosimeters and the measurement of their response as a function of energy and angle of incidence

Contents	Page
1 Scope	1
2 Normative references	1
3 Definitions	2
3.1 Quantities and units	2
3.2 Calibration factor and response determination	3
4 Procedures applicable to all area and personal dosimeters	5
4.1 General principles	5
4.2 Methods for the determination of the calibration factor and the response	9
5 Particular procedures for area dosimeters	12
5.1 General principles	12
5.2 Quantities to be measured	12
5.3 Conversion coefficients	12
6 Particular procedures for personal dosimeters	22
6.1 General principles	22
6.2 Quantities to be measured	23
6.3 Experimental conditions	23
6.4 Conversion coefficients	25
7 Presentation of results	35
7.1 Records and certificates	35
7.2 Statement of uncertainties	36
Annex A (informative) Additional information	37
Bibliography	46