

# ISO 4037-3:1999-06 (E)

X and gamma reference radiation for calibrating dosimeters and doserate meters and for determining their response as a function of photon energy - Part 3:  
Calibration of area and personal dosimeters and the measurement of their response as a function of energy and angle of incidence

---

<b>Contents</b>	<b>Page</b>
1 Scope .....	1
2 Normative references .....	1
3 Definitions .....	2
3.1 Quantities and units .....	2
3.2 Calibration factor and response determination .....	3
4 Procedures applicable to all area and personal dosimeters .....	5
4.1 General principles .....	5
4.2 Methods for the determination of the calibration factor and the response .....	9
5 Particular procedures for area dosimeters .....	12
5.1 General principles .....	12
5.2 Quantities to be measured .....	12
5.3 Conversion coefficients .....	12
6 Particular procedures for personal dosimeters .....	22
6.1 General principles .....	22
6.2 Quantities to be measured .....	23
6.3 Experimental conditions .....	23
6.4 Conversion coefficients .....	25
7 Presentation of results .....	35
7.1 Records and certificates .....	35
7.2 Statement of uncertainties .....	36
Annex A (informative) Additional information .....	37
Bibliography .....	46