

# ISO 22127:2019-12 (E)

## Dosimetry with radiophotoluminescent glass dosimeters for dosimetry audit in MV X-ray radiotherapy

---

Contents	Page
Foreword .....	v
Introduction .....	vi
1 Scope .....	1
2 Normative references .....	1
3 Terms and definitions .....	1
4 Rules for the RPLD handling/reading procedure .....	5
4.1 Principle of measurement .....	5
4.2 Objective quantity of measurement .....	6
4.3 Handling of RPLDs .....	6
4.3.1 General remarks .....	6
4.3.2 Cleaning of RPLD element .....	6
4.4 Annealing .....	6
4.5 Irradiation of RPLD .....	6
4.5.1 Effective centre of measurement .....	6
4.5.2 Irradiation dose .....	6
4.6 Pre-heating .....	6
4.7 RPLD Reading .....	7
4.7.1 General remarks .....	7
4.7.2 Positioning RPLD elements on the reading tray .....	7
4.7.3 Determination of the RPL reading .....	7
4.7.4 Reader stability compensation by reference RPLDs .....	7
5 Evaluation of absorbed dose to water .....	7
5.1 Basic formula for the determination of absorbed dose to water .....	7
5.2 Mean readings of raw data .....	8
5.3 Evaluation of background element .....	8
5.4 Individual dosimeter sensitivity correction factor of each element .....	8
5.5 Calibration coefficient with reference RPLD element .....	8
5.6 Correction factor for individual reading tray position dependence .....	9
5.7 Correction factor for the radiation quality .....	9
5.8 Correction factor for phantom material .....	10
5.9 Correction factor for nonlinearity .....	10
5.10 Uncertainty of measurement of the absorbed dose .....	11
6 Requirements for the RPLD system .....	11
6.1 General information .....	11
6.2 Recommendations concerning completeness of the RPLD system .....	11
6.2.1 Technical components .....	11
6.2.2 Hardware and software components .....	12
6.2.3 Operating instructions .....	12
6.3 Requirements for RPLD detectors .....	13
6.3.1 Characteristics of RPLD materials .....	13
6.4 Requirements for RPLD-indicating instruments .....	14
6.4.1 General remarks .....	14
6.4.2 Mechanical construction and setup .....	14
6.4.3 Repeatable reading ability .....	14

6.4.4	Indication and indication range .....	14
6.4.5	Internal calibration glass .....	14
6.4.6	Operational failure and detection .....	14
6.4.7	Data output and data backup .....	15
6.5	Requirements for auxiliary instruments (pre-irradiation annealing and pre-heat devices) .	15
6.5.1	Pre-irradiation annealing .....	15
6.5.2	Pre-heat .....	15
6.5.3	<b>Operation safety .....</b>	<b>15</b>
6.5.4	Detection of function failure .....	15
6.5.5	Indication of the operating state .....	15
	<b>Bibliography .....</b>	<b>16</b>