

# ISO 3821:2008-10 (E)

## Gas welding equipment - Rubber hoses for welding, cutting and allied processes

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Abbreviated terms .....</b>	<b>2</b>
<b>5</b>	<b>Application .....</b>	<b>2</b>
<b>6</b>	<b>Hose designation .....</b>	<b>2</b>
<b>7</b>	<b>Materials .....</b>	<b>3</b>
<b>7.1</b>	<b>Construction .....</b>	<b>3</b>
<b>7.2</b>	<b>Manufacture .....</b>	<b>3</b>
<b>8</b>	<b>Dimensions and tolerances .....</b>	<b>3</b>
<b>8.1</b>	<b>Internal diameter .....</b>	<b>3</b>
<b>8.2</b>	<b>Concentricity (total indicator reading) .....</b>	<b>4</b>
<b>8.3</b>	<b>Cut lengths and tolerances .....</b>	<b>4</b>
<b>9</b>	<b>Requirements and type tests .....</b>	<b>4</b>
<b>9.1</b>	<b>General .....</b>	<b>4</b>
<b>9.2</b>	<b>Basic requirements .....</b>	<b>4</b>
<b>9.3</b>	<b>Special requirements .....</b>	<b>6</b>
<b>10</b>	<b>Hose colour and gas identification .....</b>	<b>8</b>
<b>10.1</b>	<b>General .....</b>	<b>8</b>
<b>10.2</b>	<b>Gas identification .....</b>	<b>8</b>
<b>10.3</b>	<b>Marking .....</b>	<b>8</b>
<b>Annex A (normative) Method of test for non-ignition .....</b>		<b>9</b>
<b>Annex B (normative) Method of test for resistance to n-pentane .....</b>		<b>11</b>
<b>Annex C (normative) Method of test for resistance to incandescent particles and hot surfaces .....</b>		<b>12</b>
<b>Annex D (normative) Summary of requirements and type tests .....</b>		<b>14</b>
<b>Annex E (normative) Alternative oxygen gas colour codes .....</b>		<b>15</b>
<b>Bibliography .....</b>		<b>16</b>