

ISO 15011-3:2009-10 (E)

Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 3: Determination of ozone emission rate during arc welding

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Equipment and materials	2
6	Tests procedures	4
6.1	Welding procedure selection	4
6.2	Setting up the test equipment	4
6.3	Trial tests	5
6.4	Emission rate testing	5
7	Calculating and reporting the results	6
Annex A (informative)	Equipment notes	7
Annex B (informative)	Welding parameters for ozone emission rate testing	9
Annex C (normative)	Test procedures	11
Annex D (normative)	Calculation of the average stable ozone concentration	12
Annex E (normative)	Test report	13
Bibliography		14