

# ISO 15011-2:2009-10 (E)

Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 2: Determination of the emission rates of carbon monoxide (CO), carbon dioxide (CO<sub>2</sub>), nitrogen monoxide (NO) and nitrogen dioxide (NO<sub>2</sub>) during arc welding, cutting and gouging

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Principle .....	2
5	Equipment and materials .....	2
6	Test procedures .....	4
6.1	Welding procedure selection .....	4
6.2	Setting up the test equipment .....	4
6.3	Blank test .....	5
6.4	Manual metal arc welding .....	5
6.5	Continuous wire processes and autogeneous TIG welding .....	5
6.6	Cutting and gouging .....	6
7	Calculating and reporting the results .....	7
Annex A (informative) Possible designs of hood .....		8
Annex B (informative) Equipment notes .....		10
Annex C (informative) Welding parameters for gas-shielded arc welding .....		12
Annex D (normative) Test procedures .....		15
Annex E (normative) Calculation of the average stable gas concentration .....		16
Annex F (normative) Test report .....		17
Bibliography .....		18