

# ISO 18592:2009-12 (E)

## Resistance welding - Destructive testing of welds - Method for the fatigue testing of multi-spot-welded specimens

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>2</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>3</b>
<b>4</b>	<b>Symbols and abbreviated terms .....</b>	<b>5</b>
<b>5</b>	<b>Specimens .....</b>	<b>7</b>
5.1	General .....	7
5.2	Selection of suitable specimens .....	8
5.3	Specimen fabrication .....	10
5.4	Specimen geometry .....	11
<b>6</b>	<b>Requirements for testing machine .....</b>	<b>21</b>
<b>7</b>	<b>Specimen grips and alignment .....</b>	<b>22</b>
7.1	General .....	22
7.2	Shear and peel loading .....	23
<b>8</b>	<b>Test procedure .....</b>	<b>24</b>
8.1	General .....	24
8.2	Mounting the H-specimens .....	24
8.3	Clamping procedure for the H-specimens .....	24
8.4	Fatigue test .....	24
8.5	Test termination .....	25
<b>9</b>	<b>Test report .....</b>	<b>27</b>
9.1	Basic information .....	27
9.2	Presentation of fatigue test results .....	28
<b>Annex A (informative) Calibration specimen for verifying the load distribution in H-specimens .....</b>		<b>30</b>
<b>Annex B (informative) Hydraulic grips for the fatigue testing of H-specimens .....</b>		<b>31</b>
<b>Annex C (informative) Grip for the fatigue testing of H-specimens .....</b>		<b>32</b>
<b>Annex D (informative) Flow chart -- Data acquisition .....</b>		<b>33</b>
<b>Bibliography .....</b>		<b>36</b>