

DIN EN ISO 10882-1:2012-01 (E)

Health and safety in welding and allied processes - Sampling of airborne particles and gases in the operator's breathing zone - Part 1: Sampling of airborne particles (ISO 10882-1:2011)

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	6
3.1	General definitions	6
3.2	Sampling definitions	7
3.3	Welding terms	9
3.4	Statistical terms	11
4	Principle	12
5	Requirement	13
6	Equipment	13
6.1	Sampling equipment	13
6.2	Weighing equipment, if required	14
7	Assessment strategy	15
8	Measurement strategy	15
8.1	General	15
8.2	Personal exposure measurement	15
8.3	Fixed-point measurements	15
8.4	Selection of measurement conditions and measurement pattern	16
9	Procedure	17
9.1	Preliminary considerations	17
9.2	Preparation for sampling	18
9.3	Sampling position	19
9.4	Sampling	19
9.5	Transportation	20
9.6	Analysis	20
9.7	Expression of results	21
10	Exposure assessment	22
11	Recording of sampling data and presentation of results	22
Annex A (normative)	Gravimetric analysis	23
Annex B (informative)	Examples of arrangements for mounting samplers behind welder's face shields	25
Annex C (informative)	An example of a report	32

Annex D (informative) Blank report form	35
Bibliography	38