

# ISO 13916:1996-08 (E)

## Welding - Guidance on the measurement of preheating temperature, interpass temperature and preheat maintenance temperature

---

| <b>Contents</b>                                     |  | <b>Page</b> |
|---|--|-------------|
| Foreword .....                                      |  | IV          |
| <b>1</b> Scope .....                                |  | <b>1</b>    |
| <b>2</b> Definitions .....                          |  | <b>1</b>    |
| 2.1 Preheating temperature ( $T_p$ ) .....          |  | 1           |
| 2.2 Interpass temperature ( $T_i$ ) .....           |  | 1           |
| 2.3 Preheat maintenance temperature ( $T_m$ ) ..... |  | 1           |
| <b>3</b> Requirements .....                         |  | <b>1</b>    |
| 3.1 Point of measurement .....                      |  | 1           |
| 3.2 Time of measurement .....                       |  | 2           |
| 3.3 Test equipment .....                            |  | 3           |
| <b>4</b> Test report .....                          |  | <b>3</b>    |
| <b>5</b> Designation .....                          |  | <b>3</b>    |