

# ISO 10882-2:2000-09 (E)

Health and safety in welding and allied processes\_ - Sampling of airborne particles and gases  
in the operator's breathing zone\_ - Part\_2: Sampling of gases

---

Contents	Page
Foreword.....	v
Introduction .....	vi
1 Scope .....	1
2 Normative references .....	2
3 Terms and definitions.....	2
4 Description of measurement methods .....	6
4.1 General.....	6
4.2 Direct reading electrical apparatus.....	7
4.3 Detector tubes.....	7
4.4 Indirect methods involving laboratory analysis .....	8
5 Requirements .....	9
6 Assessment strategy.....	9
7 Measurement strategy.....	10
7.1 General.....	10
7.2 Personal exposure measurements .....	10
7.3 Fixed point measurements .....	10
7.4 Selection of measurement conditions and measurement pattern.....	10
8 Sampling.....	11
8.1 Sampling position.....	11
8.2 Sampling equipment.....	11
8.3 Sample filtration.....	12
8.4 Multiple sampling.....	12
8.5 Volume of sampling line.....	12
8.6 Flow rate .....	12
8.7 Handling of temperature, pressure and humidity data .....	12
9 Measurement of individual gases and vapours.....	13
9.1 General.....	13
9.2 Ozone (0,01 ppm to 3 ppm).....	13
9.3 Carbon monoxide (3 ppm to 500 ppm) .....	13
9.4 Carbon dioxide (500 ppm to 10 %).....	14
9.5 Nitric oxide (1 ppm to 100 ppm) and nitrogen dioxide (0,3 ppm to 250 ppm) .....	14
9.6 Vapours.....	15
10 Recording of test data and presentation of results .....	16
Annex A (Informative) Measurement of individual gases and vapours .....	17
Annex B (informative) An example of a test report.....	18
B.1 Basic data .....	18
B.2 Process data.....	19
B.3 Sampling data and test results.....	20
Bibliography .....	21