

ISO/TS 8182:2026-08 (E)

Welding and allied processes - Requirements and recommendations for the use of the welding parameters related to the arc energy for qualification and specification of welding procedures

Contents

Page

Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and abbreviated terms	2
5 Risk levels	3
6 Measuring welding parameters during WPQR welding	3
6.1 Calibration, validation of the measuring equipment	3
6.2 Determination of runs to be measured	4
6.3 Length of run in pipe and plate	4
6.4 Weaving width in relation with arc energy	4
6.5 Arc voltage, welding current, length of the run, welding speed, arc energy and temperature	4
6.5.1 General	4
6.5.2 Arc voltage (U)	5
6.5.3 Welding current (I)	5
6.5.4 Length of the run	5
6.5.5 Welding speed	5
6.5.6 Arc energy	5
6.5.7 Preheat temperature	5
6.5.8 Interpass temperature	5
7 Reporting welding variables to a WPQR	5
8 Transferring WPQR welding parameters to a WPS	6
8.1 Welding areas	6
8.2 Thickness	6
8.3 Arc-voltage, welding current and welding speed in relation to arc energy	7
8.4 Relation preheat- and interpass temperature and arc energy	7
8.5 Weaving width in relation with arc energy	7
9 Measuring welding parameters during production welding	7
9.1 Calibration, validation of the measuring equipment	7
9.2 Determination of several weld areas	7
9.2.1 Length of the run in pipe and plate	8
9.3 Weaving width in relation with arc energy	8
9.4 Preheat temperature	8
9.5 Interpass temperature	8
Annex A (informative) Example WPQR sheet for a weld divided in several weld areas	9
Annex B (informative) Example sheet WPS with alternative calculation of arc energy based on Annex A and the applicable risk level	10
Bibliography	11