

ISO 15618-2:2001-12 (E)

Qualification testing of welders for underwater welding_ - Part_2: Diver-welders and welding operators for hyperbaric dry welding

Contents

	Page
Foreword	v
Introduction	1
1 Scope	1
2 Normative references	1
3 Terms and definitions	3
4 Symbols and abbreviations	3
4.1 General	3
4.2 Test piece	3
4.3 Consumable	3
4.4 Miscellaneous	3
5 Essential variables for approval testing	4
5.1 General	4
5.2 Welding processes	4
5.3 Joint types (butt and fillet welds)	4
5.4 Material groups	4
5.5 Consumables	4
5.6 Dimensions	5
5.7 Welding positions	5
5.8 Hyperbaric environment	5
6 Range of approval	5
6.1 General	5
6.2 Welding process	6
6.3 Joint types	6
6.4 Material groups	7
6.5 Consumables	7
6.6 Dimensions	7
6.7 Welding positions	7
6.8 Hyperbaric environment	8
7 Examination and testing	9
7.1 General	9
7.2 Supervision	9
7.3 Shapes and dimensions of test pieces	9
7.4 Welding conditions	11
7.5 Test methods	11
7.6 Test pieces and test specimens	12
8 Acceptance requirements for test pieces	16
9 Re-tests	16
10 Period of validity	17
10.1 Initial approval	17
10.2 Prolongation	17
11 Certificate	17
12 Designation	18
Annex A (informative) Diver-welder or welding operator approval test certificate for hyperbaric dry welding	19
Annex B (informative) Job knowledge	21