

# ISO 17846:2004-05 (E)

## Welding and allied processes - Health and safety - Wordless precautionary labels for equipment and consumables used in arc welding and cutting

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Requirements for wordless precautionary labels .....	2
4.1	Use of precautionary labels on products .....	2
4.2	Label elements .....	2
4.3	Design of precautionary labels .....	2
4.4	Use of symbols .....	2
4.5	Uniformity of symbols .....	2
4.6	Label legibility, placement, visibility, and durability .....	3
4.7	The basic precautionary label .....	3
4.8	The wordless label for plasma arc cutting equipment .....	3
4.9	The precautionary label for engine-driven welding and cutting equipment .....	3
4.10	The precautionary label for wire feeding equipment .....	3
4.11	Precautionary labels for other hazards .....	3
	Annex A (informative) Precautionary label symbols .....	4
	Annex B (informative) Examples of wordless precautionary labels .....	10
	Bibliography .....	18