

ISO 21438-1:2007-12 (E)

Workplace atmospheres - Determination of inorganic acids by ion chromatography - Part 1: Non-volatile acids (sulfuric acid and phosphoric acid)

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
3.1	General definitions	2
3.2	Particle size fraction definitions	3
3.3	Sampling definitions	3
3.4	Analytical definitions	4
3.5	Statistical terms	5
4	Principle	6
5	Requirement	7
6	Reagents	7
7	Apparatus	9
7.1	Sampling equipment	9
7.2	Laboratory apparatus	11
8	Occupational exposure assessment	12
8.1	General	12
8.2	Personal sampling	12
8.3	Static sampling	12
8.4	Selection of measurement conditions and measurement pattern	13
9	Sampling	14
9.1	Preliminary considerations	14
9.2	Preparation for sampling	16
9.3	Sampling position	16
9.4	Collection of samples	17
9.5	Transportation	17
10	Analysis	18
10.1	Preparation of test and calibration solutions	18
10.2	Instrumental analysis	19
10.3	Estimation of detection and quantification limits	20
10.4	Quality control	21
10.5	Measurement uncertainty	21
11	Expression of results	22
12	Method performance	22
12.1	Sample collection and stability	22
12.2	Quantification limits	22
12.3	Upper limits of the analytical range	22

12.4	Bias and precision	23
12.5	Uncertainty of sampling and analysis method	23
12.6	Interferences	23
13	Test report	24
13.1	Test record	24
13.2	Laboratory report	25
Annex A (informative) Temperature and pressure correction		26
Bibliography		28