

DIN EN 1076:2010-04 (E)

Workplace exposure - Procedures for measuring gases and vapours using pumped samplers - Requirements and test methods

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Symbols and abbreviated terms	5
5	Types of samplers	7
6	Requirements	7
6.1	General	7
6.2	Sampler requirements	7
6.3	Measuring procedure requirements	10
7	General test conditions	12
7.1	Reagents	12
7.2	Apparatus	12
7.3	Independent method	13
7.4	Generation of the calibration gas mixture	13
8	Test methods	14
8.1	General	14
8.2	Sampler test methods	14
8.3	Measuring procedure test methods	15
8.4	Uncertainty of measurement	22
9	Test report	23
Annex A (informative) Examples for the determination of the breakthrough volume		24
A.1	Direct method	24
A.2	Chromatographic method	24
Annex B (informative) Estimation of uncertainty of measurement		26
B.1	General	26
B.2	Uncertainty associated with sampled air volume	26
B.3	Uncertainty associated with sampling efficiency	28
B.4	Uncertainty associated with sample storage and transportation	28
B.5	Uncertainty associated with method recovery	28
B.6	Uncertainty associated with method variability	32
B.7	Calculation of combined standard uncertainty	35
Annex C (informative) Example of estimation of expanded uncertainty		37
Bibliography		41