

# ISO 30011:2010-10 (E)

## Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma mass spectrometry

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>2</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
3.1	General definitions .....	2
3.2	Analytical definitions .....	3
3.3	ICP-MS definitions .....	6
3.4	Statistical definitions .....	8
<b>4</b>	<b>Principle .....</b>	<b>10</b>
<b>5</b>	<b>Requirements .....</b>	<b>10</b>
<b>6</b>	<b>Reagents .....</b>	<b>10</b>
<b>7</b>	<b>Laboratory apparatus .....</b>	<b>13</b>
<b>8</b>	<b>Procedure .....</b>	<b>13</b>
8.1	Preparation of sample solutions .....	13
8.2	Method development .....	14
8.3	Instrument performance checks .....	18
8.4	Routine analysis .....	18
8.5	Estimation of detection and quantification limits .....	20
8.6	Quality control .....	20
8.7	Measurement uncertainty .....	21
<b>9</b>	<b>Expression of results .....</b>	<b>22</b>
<b>10</b>	<b>Method performance .....</b>	<b>22</b>
10.1	Method detection limits and quantification limits .....	22
10.2	Upper limits of the analytical range .....	22
10.3	Bias and precision .....	23
10.4	Measurement uncertainty .....	24
<b>11</b>	<b>Test report .....</b>	<b>24</b>
11.1	Test records .....	24
11.2	Laboratory report .....	25
<b>Annex A (informative) ICP-MS principles and interferences .....</b>		<b>26</b>
<b>Annex B (informative) Guidance on maintenance of ICP-MS instrumentation .....</b>		<b>29</b>
<b>Annex C (informative) Recalculation of metal and metalloid in air concentrations to reference conditions .....</b>		<b>31</b>
<b>Bibliography .....</b>		<b>32</b>