

ISO 15202-1:2012-06 (E)

Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma atomic emission spectrometry - Part 1: Sampling

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
3.1	General definitions	2
3.2	Particle size fraction definitions	3
3.3	Sampling definitions	4
4	Principle	4
5	Requirement	4
6	Sampling equipment	5
6.1	Samplers	5
6.2	Filters	5
6.3	Sampling pumps	5
6.4	Flowmeter	6
6.5	Ancillary equipment	6
7	Occupational exposure assessment	7
7.1	General	7
7.2	Personal sampling	7
7.3	Static sampling	7
7.4	Selection of measurement conditions and measurement pattern	7
8	Sampling method	8
8.1	Preliminary considerations	8
8.2	Preparation for sampling	9
8.3	Sampling position	10
8.4	Collection of samples	11
8.5	Transportation	11
9	Documentation	11
9.1	Sampling information	11
9.2	Information to accompany the request for analytical services	12
Annex A (informative) Sampler wall deposits		13
Annex B (informative) Guidance on filter selection		15
Annex C (informative) Temperature and pressure correction for the indicated volumetric flow rate		17
Bibliography		18