

# ISO 15202-1:2012-06 (E)

## Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma atomic emission spectrometry - Part 1: Sampling

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
3.1	General definitions .....	2
3.2	Particle size fraction definitions .....	3
3.3	Sampling definitions .....	4
4	Principle .....	4
5	Requirement .....	4
6	Sampling equipment .....	5
6.1	Samplers .....	5
6.2	Filters .....	5
6.3	Sampling pumps .....	5
6.4	Flowmeter .....	6
6.5	Ancillary equipment .....	6
7	Occupational exposure assessment .....	7
7.1	General .....	7
7.2	Personal sampling .....	7
7.3	Static sampling .....	7
7.4	Selection of measurement conditions and measurement pattern .....	7
8	Sampling method .....	8
8.1	Preliminary considerations .....	8
8.2	Preparation for sampling .....	9
8.3	Sampling position .....	10
8.4	Collection of samples .....	11
8.5	Transportation .....	11
9	Documentation .....	11
9.1	Sampling information .....	11
9.2	Information to accompany the request for analytical services .....	12
Annex A (informative) Sampler wall deposits .....		13
Annex B (informative) Guidance on filter selection .....		15
Annex C (informative) Temperature and pressure correction for the indicated volumetric flow rate .....		17
Bibliography .....		18