

# DIN EN 15051-3:2014-03 (E)

## Workplace exposure - Measurement of the dustiness of bulk materials - Part 3: Continuous drop method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	5
4	Requirements .....	6
4.1	General .....	6
4.2	Condition of the bulk material .....	6
4.3	Sample and environmental control .....	6
4.4	Moisture content .....	6
4.5	Bulk density .....	6
4.6	Test procedure .....	6
4.7	Replicate tests .....	6
4.8	Reporting .....	6
5	Continuous drop method .....	6
5.1	Description of test apparatus .....	6
5.2	Filters .....	8
5.3	Ancillary equipment .....	8
5.4	Preparation of test sample .....	8
5.5	Preparation of test apparatus .....	9
5.6	Test procedure .....	9
5.7	Weighing the filters .....	9
5.8	Determination of the inhalable and respirable dustiness mass fractions .....	10
6	Evaluation of dustiness .....	10
7	Test report .....	11
Bibliography .....		12