

# ISO 24095:2021-09 (E)

## Workplace air - Guidance for the measurement of respirable crystalline silica

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Principle .....	2
5	Analytical quality requirements .....	3
6	Administrative controls .....	3
7	Sampling .....	4
7.1	General .....	4
7.2	Sampler .....	4
7.3	Filters and foams .....	4
7.4	Sampling flow measurement devices and pumps .....	5
7.5	Sampling period .....	5
7.6	Transportation .....	6
8	Procedures .....	7
8.1	Handling of filter cassettes .....	7
8.2	Method validation .....	7
8.3	Calibration .....	7
8.4	Sample preparation .....	8
8.5	Sample measurement .....	9
8.5.1	Limit of Detection .....	9
8.5.2	X-ray diffraction .....	9
8.5.3	Infrared analysis .....	9
8.6	Instrumental variation .....	10
8.6.1	X-ray diffraction .....	10
8.6.2	Infrared analysis .....	10
9	Internal quality control .....	10
10	External verification and assessment of uncertainty .....	11
11	Test report .....	11
11.1	Minimum report requirements .....	11
11.2	Data to be archived by the laboratory .....	12
Annex A (informative) Polymorphs of crystalline silica and their interferences .....		13
Annex B (informative) The quantification of cristobalite using X-ray diffraction .....		19
Annex C (informative) Example of quality control charting for respirable crystalline silica .....		23

<b>Annex D (informative) Estimation of expanded uncertainty for measurements of respirable crystalline silica .....</b>	<b>25</b>
<b>Annex E (informative) Differences between samplers (cyclones and other types) .....</b>	<b>35</b>
<b>Annex F (informative) Use of proficiency test data to evaluate the performance of XRD and IR methods in the presence of interferences .....</b>	<b>37</b>
<b>Bibliography .....</b>	<b>42</b>