

ISO 21438-1:2022-05 (E)

Workplace atmospheres - Determination of inorganic acids by ion chromatography - Part 1: Non-volatile acids (sulfuric acid and phosphoric acid)

| Contents | | Page |
|-----------------|--|-------------|
| Foreword | | v |
| Introduction | | vi |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 2 |
| 4 | Principle | 3 |
| 5 | Requirement | 3 |
| 6 | Reagents | 3 |
| 7 | Apparatus | 4 |
| | 7.1 Sampling equipment | 4 |
| | 7.2 Laboratory apparatus | 6 |
| 8 | Occupational exposure assessment | 7 |
| 9 | Sampling | 7 |
| | 9.1 Preliminary considerations | 7 |
| | 9.1.1 Selection and use of samplers | 7 |
| | 9.1.2 Sampling period | 7 |
| | 9.1.3 Effect of temperature and pressure on flow rate measurements | 7 |
| | 9.1.4 Sample handling | 8 |
| | 9.1.5 Sampling interferences | 8 |
| | 9.2 Preparation for sampling | 8 |
| | 9.2.1 Cleaning of samplers | 8 |
| | 9.2.2 Loading the samplers with filters | 9 |
| | 9.2.3 Setting the volumetric flow rate | 9 |
| | 9.2.4 Field blanks | 9 |
| | 9.3 Sampling position | 9 |
| | 9.3.1 Personal sampling | 9 |
| | 9.3.2 Static sampling | 9 |
| | 9.4 Collection of samples | 9 |
| | 9.5 Transportation | 10 |
| | 9.5.1 Samplers that collect airborne particles on the filter | 10 |
| | 9.5.2 Samplers with an internal filter cassette | 10 |
| | 9.5.3 Samplers of the disposable cassette type | 10 |
| | 9.5.4 Transport of samples to the laboratory | 11 |
| 10 | Analysis | 11 |
| | 10.1 Preparation of test, calibration solutions and filter samples | 11 |
| | 10.1.1 General | 11 |
| | 10.1.2 Quartz fibre filters | 11 |
| | 10.1.3 PVC and PTFE filters | 11 |
| | 10.1.4 Preparation of calibration solutions | 12 |
| | 10.2 Instrumental analysis | 12 |
| | 10.3 Estimation of detection and quantification limits | 13 |
| | 10.3.1 Estimation of the instrumental detection limits | 13 |
| | 10.3.2 Estimation of the method detection limit and quantification limit | 13 |
| | 10.4 Quality control | 13 |
| | 10.4.1 Reagent blanks and laboratory blanks | 13 |

| | | |
|-----------|---|-----------|
| 10.4.2 | Quality control solutions..... | 14 |
| 10.4.3 | Certified reference materials..... | 14 |
| 10.4.4 | External quality assessment..... | 14 |
| 10.5 | Measurement uncertainty..... | 14 |
| 11 | Expression of results..... | 15 |
| 12 | Method performance..... | 15 |
| 12.1 | Sample collection and stability..... | 15 |
| 12.2 | Quantification limits..... | 15 |
| 12.3 | Upper limits of the analytical range..... | 15 |
| 12.4 | Bias and precision..... | 16 |
| 12.4.1 | Analytical bias..... | 16 |
| 12.4.2 | Analytical precision..... | 16 |
| 12.5 | Uncertainty of sampling and analysis method..... | 16 |
| 12.6 | Interferences..... | 16 |
| 13 | Test report..... | 17 |
| 13.1 | Test record..... | 17 |
| 13.2 | Laboratory report..... | 18 |
| | Annex A (informative) Temperature and pressure correction..... | 19 |
| | Bibliography..... | 21 |