

# ISO 11174:2023-05 (E)

## Workplace air - Determination of particulate cadmium and cadmium compounds - Flame and electrothermal atomic absorption spectrometric method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	2
4	Principle .....	2
5	Reactions .....	3
6	Requirement .....	3
7	Reagents .....	3
8	Apparatus .....	5
9	Sampling .....	8
9.1	Sampling procedure .....	8
9.1.1	Collection characteristics and flow rate .....	8
9.1.2	Sampling period .....	8
9.1.3	Temperature and pressure effects .....	8
9.2	Preparation of sampling equipment .....	9
9.3	Collection of samples .....	9
9.4	Transportation .....	10
10	Procedure for analysis .....	10
10.1	Cleaning of glassware and polypropylene bottles .....	10
10.2	Preparation of sample solutions and blank test solutions .....	11
10.3	Analysis by flame atomic absorption spectrometry .....	11
10.3.1	General .....	11
10.3.2	Preparation of calibration solutions .....	12
10.3.3	Calibration .....	12
10.3.4	Determination .....	12
10.4	Analysis by electrothermal atomic absorption spectrometry .....	13
10.4.1	General .....	13
10.4.2	Preparation of working calibration solutions .....	13
10.4.3	Calibration and determination .....	13
10.5	Estimation of the instrumental detection limit .....	15
11	Expression of results .....	15
11.1	Calculations .....	15
11.2	Performance of the method .....	16
11.3	Detection limit and working range .....	17
12	Special cases .....	18
13	Test report .....	18
Annex A (informative)	Typical operating parameters for determination of cadmium by electrothermal atomic absorption spectrometry .....	20
Bibliography .....		21