

ISO 11174:2023-05 (E)

Workplace air - Determination of particulate cadmium and cadmium compounds - Flame and electrothermal atomic absorption spectrometric method

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Principle	2
5	Reactions	3
6	Requirement	3
7	Reagents	3
8	Apparatus	5
9	Sampling	8
9.1	Sampling procedure	8
9.1.1	Collection characteristics and flow rate	8
9.1.2	Sampling period	8
9.1.3	Temperature and pressure effects	8
9.2	Preparation of sampling equipment	9
9.3	Collection of samples	9
9.4	Transportation	10
10	Procedure for analysis	10
10.1	Cleaning of glassware and polypropylene bottles	10
10.2	Preparation of sample solutions and blank test solutions	11
10.3	Analysis by flame atomic absorption spectrometry	11
10.3.1	General	11
10.3.2	Preparation of calibration solutions	12
10.3.3	Calibration	12
10.3.4	Determination	12
10.4	Analysis by electrothermal atomic absorption spectrometry	13
10.4.1	General	13
10.4.2	Preparation of working calibration solutions	13
10.4.3	Calibration and determination	13
10.5	Estimation of the instrumental detection limit	15
11	Expression of results	15
11.1	Calculations	15
11.2	Performance of the method	16
11.3	Detection limit and working range	17
12	Special cases	18
13	Test report	18
Annex A (informative)	Typical operating parameters for determination of cadmium by electrothermal atomic absorption spectrometry	20
Bibliography		21