

ISO 21438-2:2024-01 (E)

Workplace atmospheres - Determination of inorganic acids by ion chromatography - Part 2: Volatile acids, except hydrofluoric acid (hydrochloric acid, hydrobromic acid and nitric acid)

Contents

Page

Foreword.....	v
Introduction.....	vi
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
4 Principle	3
5 Requirement	3
6 Reagents	3
7 Apparatus	4
7.1 Sampling equipment.....	4
7.2 Laboratory apparatus.....	5
8 Occupational exposure assessment	6
9 Sampling	7
9.1 Preliminary considerations.....	7
9.1.1 Selection and use of samplers.....	7
9.1.2 Sampling period.....	7
9.1.3 Effect of temperature and pressure on flow rate measurements.....	8
9.1.4 Sample handling.....	8
9.2 Preparation for sampling.....	8
9.2.1 Cleaning of samplers.....	8
9.2.2 Loading the aerosol samplers with filters.....	8
9.2.3 Setting the volumetric flow rate.....	9
9.2.4 Field blanks.....	9
9.3 Sampling position.....	9
9.3.1 Personal sampling.....	9
9.3.2 Static sampling.....	9
9.4 Collection of samples.....	9
9.5 Transportation.....	10
9.5.1 Samplers that collect airborne particles and/or gases on the filter.....	10
9.5.2 Samplers with an internal filter cassette.....	10
9.5.3 Samplers of the disposable-cassette type.....	10
9.5.4 Transport of samples to the laboratory.....	10
9.5.5 Equilibration period.....	10
10 Analysis	10
10.1 Preparation of test and calibration solutions, and filter samples.....	11
10.1.1 General.....	11
10.1.2 Preparation of filter solutions.....	11
10.1.3 Preparation of calibration solutions.....	11
10.2 Instrumental analysis.....	11
10.3 Estimation of limits of detection and quantification.....	12
10.3.1 Estimation of the instrumental limit of detection.....	12
10.3.2 Estimation of the method limit of detection and limit of quantification.....	12
10.4 Quality control.....	12

10.4.1	Reagent blanks and laboratory blanks.....	12
10.4.2	Quality control solutions.....	12
10.4.3	Certified reference materials.....	13
10.4.4	Proficiency testing.....	13
10.5	Measurement uncertainty.....	13
11	Expression of results.....	13
12	Method performance.....	14
12.1	Sampling efficiency and sample storage.....	14
12.2	Limits of quantification.....	14
12.3	Upper limits of the working range.....	14
12.4	Bias and precision.....	14
12.4.1	Analytical bias.....	14
12.4.2	Analytical precision.....	15
12.5	Uncertainty of sampling and analysis method.....	15
12.6	Interferences.....	15
13	Test report.....	15
13.1	Test record.....	15
13.2	Laboratory report.....	16
Annex A	(normative) Temperature and pressure correction.....	17
Annex B	(informative) Filter materials.....	19
Bibliography		20