

# ISO 22578-2:2024-02 (E)

## Graphical symbols - Safety colours and safety signs - Part 2: Measurement of photopic luminance of phosphorescent components used in a natural disaster safety way guidance system

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Test specification .....	1
4.1	Test specimens .....	1
4.2	Conditioning .....	2
4.3	Ambient conditions .....	2
4.4	Irradiance, illuminance and luminance instrumentation .....	2
4.4.1	Irradiance instrumentation .....	2
4.4.2	Illuminance instrumentation .....	2
4.4.3	Luminance instrumentation .....	3
4.5	Excitation light conditions .....	3
4.6	Luminance measurements .....	3
4.6.1	General .....	3
4.6.2	Telephotometer method .....	3
4.6.3	Contact method .....	3
4.6.4	Luminance recordings .....	4
4.7	Test report .....	4
4.8	Marking of phosphorescent materials .....	5
Bibliography .....		6