

DIN EN 15051-1:2026-01 (E)

Workplace exposure - Measurement of the dustiness of bulk materials - Part 1: Requirements and choice of test methods

Contents		Page
European foreword		3
Introduction		4
1	Scope	6
2	Normative references	6
3	Terms and definitions	6
4	Principle	7
5	General procedures	7
5.1	Schematic overview of the procedure	7
5.2	Conditioning of the bulk material	8
5.2.1	As-received condition	8
5.2.2	Conditioning specifications	9
5.3	Sample and environmental control	9
5.4	Taking samples from the bulk material	9
5.5	Moisture content	10
5.6	Bulk density	10
5.7	Test procedure	10
5.8	Replicate tests	10
5.9	In-house test powder	10
5.10	Reporting	10
6	Test methods	10
6.1	Description of the methods	10
6.2	Selection of the most appropriate test method	11
7	Evaluation of dustiness	11
8	Test report	12
Annex A (normative) Determination of moisture content		13
Annex B (normative) Determination of bulk density of the test material		15
Annex C (informative) Spheriglass 5000 CP00 - An example of a suitable powder for quality purposes		16
Bibliography		17