

ISO 21438-3:2026-01 (E)

Workplace atmospheres - Determination of inorganic acids by ion chromatography - Part 3: Hydrofluoric acid and particulate fluorides

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Requirement	3
6	Reagents	3
7	Apparatus	4
7.1	Sampling equipment	4
7.2	Laboratory apparatus	5
8	Occupational exposure assessment	6
9	Sampling	6
9.1	Preliminary considerations	6
9.1.1	Selection and use of samplers	6
9.1.2	Sampling period	6
9.1.3	Effect of temperature and pressure on flow rate measurements	7
9.1.4	Sample handling	7
9.2	Preparation for sampling	8
9.2.1	Cleaning of samplers	8
9.2.2	Loading the samplers with filters	8
9.2.3	Setting the volumetric flow rate	8
9.2.4	Field blanks	8
9.3	Sampling position	9
9.3.1	Personal sampling	9
9.3.2	Static sampling	9
9.4	Collection of samples	9
9.5	Transportation	10
9.5.1	Samplers that collect either airborne particles or gases, or both, on the filter	10
9.5.2	Sampler with an internal filter cassette	10
9.5.3	Samplers of the disposable cassette type	10
9.5.4	Transport of samples to the laboratory	10
10	Analysis	10
10.1	General	10
10.2	Preparation of test and calibration solutions	10
10.2.1	General	10
10.2.2	Selection of sample preparation method	10
10.2.3	Preparation of test solutions	10
10.2.4	Preparation of calibration solutions	11
10.3	Instrument analysis	11
10.4	Estimate of limits of detection (LODs) and limits of quantification (LOQs)	12
10.4.1	Estimation of the instrumental limit of detection	12
10.4.2	Estimation of the method limits of detection and limits of quantification	12
10.5	Quality control	12
10.5.1	Reagent blanks and laboratory blanks	12
10.5.2	Quality control solutions	12

10.5.3	Certified reference materials.....	13
10.6	Measurement uncertainty.....	13
11	Expression of results	13
12	Method performance	14
12.1	Sampling efficiency and sample storage	14
12.1.1	HF.....	14
12.1.2	Particulate fluorides	14
12.1.3	Humidity.....	14
12.2	Limit of quantification.....	15
12.3	Upper limits of the measuring range.....	15
12.4	Bias and precision.....	15
12.4.1	Analytical bias.....	15
12.4.2	Analytical precision.....	15
12.5	Uncertainty of sampling and analysis method	15
12.6	Interferences.....	15
13	Test report	15
Annex A	(informative) Temperature and pressure correction	17
Annex B	(informative) Filter materials	20
Bibliography	21