

# ISO 16740:2005-02 (E)

## Workplace air - Determination of hexavalent chromium in airborne particulate matter - Method by ion chromatography and spectrophotometric measurement using diphenyl carbazide

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>3.1</b>	<b>General definitions .....</b>	<b>2</b>
<b>3.2</b>	<b>Particle size fraction definitions .....</b>	<b>3</b>
<b>3.3</b>	<b>Sampling definitions .....</b>	<b>3</b>
<b>3.4</b>	<b>Analytical definitions .....</b>	<b>4</b>
<b>3.5</b>	<b>Statistical terms .....</b>	<b>5</b>
<b>4</b>	<b>Principle .....</b>	<b>6</b>
<b>5</b>	<b>Reactions .....</b>	<b>7</b>
<b>6</b>	<b>Requirement .....</b>	<b>7</b>
<b>7</b>	<b>Reagents .....</b>	<b>7</b>
<b>8</b>	<b>Apparatus .....</b>	<b>10</b>
<b>8.1</b>	<b>Sampling equipment .....</b>	<b>10</b>
<b>8.2</b>	<b>Laboratory apparatus .....</b>	<b>12</b>
<b>9</b>	<b>Occupational exposure assessment .....</b>	<b>15</b>
<b>9.1</b>	<b>General .....</b>	<b>15</b>
<b>9.2</b>	<b>Personal sampling .....</b>	<b>15</b>
<b>9.3</b>	<b>Static sampling .....</b>	<b>16</b>
<b>9.4</b>	<b>Selection of measurement conditions and measurement pattern .....</b>	<b>16</b>
<b>10</b>	<b>Sampling method .....</b>	<b>17</b>
<b>10.1</b>	<b>Preliminary considerations .....</b>	<b>17</b>
<b>10.2</b>	<b>Preparation for sampling .....</b>	<b>18</b>
<b>10.3</b>	<b>Sampling position .....</b>	<b>19</b>
<b>10.4</b>	<b>Collection of samples .....</b>	<b>19</b>
<b>10.5</b>	<b>Transportation .....</b>	<b>20</b>
<b>11</b>	<b>Analysis .....</b>	<b>21</b>
<b>11.1</b>	<b>Analytical requirements .....</b>	<b>21</b>
<b>11.2</b>	<b>Preparation of solutions for determination of soluble hexavalent chromium compounds .....</b>	<b>22</b>
<b>11.3</b>	<b>Preparation of solutions for determination of insoluble hexavalent chromium compounds .....</b>	<b>23</b>
<b>11.4</b>	<b>Instrumental analysis .....</b>	<b>25</b>
<b>11.5</b>	<b>Estimation of detection and quantification limits .....</b>	<b>27</b>
<b>11.6</b>	<b>Quality control .....</b>	<b>27</b>
<b>11.7</b>	<b>Measurement uncertainty .....</b>	<b>28</b>

<b>12</b>	<b>Expression of results .....</b>	<b>28</b>
<b>13</b>	<b>Method performance .....</b>	<b>29</b>
<b>13.1</b>	<b>Sample collection and stability .....</b>	<b>29</b>
<b>13.2</b>	<b>Hotplate extraction .....</b>	<b>29</b>
<b>13.3</b>	<b>Ultrasonic extraction .....</b>	<b>29</b>
<b>13.4</b>	<b>Interferences .....</b>	<b>29</b>
<b>14</b>	<b>Special cases .....</b>	<b>30</b>
<b>14.1</b>	<b>Spray-painting .....</b>	<b>30</b>
<b>14.2</b>	<b>Action to be taken when particles have become dislodged from the filter during transportation .....</b>	<b>30</b>
<b>15</b>	<b>Test report .....</b>	<b>30</b>
<b>15.1</b>	<b>Test record .....</b>	<b>30</b>
<b>15.2</b>	<b>Laboratory report .....</b>	<b>31</b>
	<b>Annex A (informative) Temperature and pressure corrections .....</b>	<b>32</b>
	<b>Annex B (informative) Background on methods for determination of hexavalent chromium in air and guidance on their use .....</b>	<b>34</b>
	<b>Bibliography .....</b>	<b>38</b>